

BERMUDA GREENS CONDOMINIUM ASSOCIATION, INC.
NOTICE OF MEETING OF THE BOARD OF DIRECTORS

NOTICE is hereby given of a meeting of the Board of Directors at the date, time, and location shown below:

Call in Instructions Only: (US) 1-929-205-6099, Meeting ID: 854 8833 9696,
Passcode: 827046

Date: Tuesday October 20, 2026

Time: 3:00 p.m. Eastern Time (US and Canada)

Location:

Onsite Meeting at Clubhouse, 13136 Castle Harbour Drive, Naples, FL 34110

Remote: If calling in, please mute your phone or computer unless asked to speak

AGENDA:

1. Call to Order
2. Proof of Notice
3. Establish a Quorum
4. Disposition of Meeting Minutes
5. President's Report
6. Treasurer's Report
7. Manager's Report
 - a. Sales & Leases
8. Committee Reports (If applicable):
 - a. Rules & Regulations Committee
 - b. Landscaping Committee
 - c. ARC Committee
 - d. Website Committee
 - e. Social Committee
 - f. Bocce Committee
 - g. Long Term Planning Committee
9. Old Business
 - a. Updated owner's Directory
10. New Business
 - a. Amend ARC Guideline document to further define new window installation issues for second floor units (see attached).
 - b. Next steps to address concrete issues in 2027 based upon LTP concrete sub-committee report (see attached).
 - c. Consideration of possible new pool maintenance providers for 2027.

d. Next step to determine whether to repair existing swimming pool geothermal heating/cooling system or completely replace in 2027.

11. Owner's Forum

12. Adjournment

ZOOM INFORMATION

BG Secretary is inviting you to a scheduled Zoom meeting.

Topic: BG Board Meeting

Date: Tuesday , 2026

Time: 3:00 PM Eastern Time (US and Canada)

Join Zoom Meeting

<https://us06web.zoom.us/j/85488339696?pwd=amPYhHkrC3lU5fbGcEC7PGq2rZ7hwL1>

Meeting ID: 854 8833 9696

Passcode: 827046

One tap mobile

+13017158592,,85488339696#,,, *827046# US (Washington DC)

+13052241968,,85488339696#,,, *827046# US

Dial by your location

- +1 929 436 2866 US (New York)

- +41 31 528 09 88 Switzerland

Meeting ID: 854 8833 9696

Passcode: 827046

Find your local number: <https://us06web.zoom.us/j/kd4Kg6PzHe>

NASSAU POOLS, INC.

1860 J&C Boulevard
Naples, FL, 34109
License #CPC1456809

August 13, 2026

Bermuda Greens HOA

13136 Castle Harbour Dr.
Naples, FL 34110
ATTN: sara@camswfl.com

Please see below our service contract for monthly maintenance at Bermuda Greens noted above. The pricing is valid for 30 days from the date of the proposal. A signed contract is required to commence with a maintenance program.

Standard 5X1 Maintenance Program

1. Test pool/spa water for chlorine and adjust as necessary.
2. Test pool/spa water for pH and adjust as necessary.
3. Test pool/spa water for total alkalinity and adjust as necessary.
4. Test pool/spa water for cyanuric acid and adjust as necessary.
5. Test pool/spa water for salt content – if applicable and adjust as necessary.
6. Vacuum pool/spa – 1X per week. Additional vacuums are billed at \$75 per hour
7. Clean tiles on pool/spa- as needed to remove debris/mold/prevent algae.
8. Brush walls on pool/spa as needed to remove debris and prevent algae.
9. Net/skim surface of pool/spa as needed to remove debris.
10. Check equipment weekly and report issues for approval and repair.
11. Backwash filters as necessary.
12. Fill out HD form as required.

5x1: Items 1 through 10 include needed chemicals for the sum of \$1,500.00per month.

NOTE: All services will be performed under normal weather conditions. Cases of exceptional weather, (gale force winds, hurricanes, tropical storms) or pressure washing of decks or homes may cause additional expenses to owners.

NOTE: The route technician that will take care of the pool will be the same person pending illness or vacation. The route technician, along with anyone that would fill in during an absence, are licensed and insured as well as have all the accreditations required to take care of a commercial pool in Lee and Collier Counties.

NOTE: WEEKEND 911 LINE / AFTER HOURS LINE. Our weekend 911/Emergency line is available 24/7/365 by calling our main line at 239-597-2112 and following the prompts, using button 2. We have a cleaning and repair technician on call during the evenings and weekends. Our labor rate for weekend or after-hours emergency calls is \$250 per hour.

NOTE: BILLING – Invoices are sent out on the 25th of the month for the following month.

NOTE: CANCELLATION OF SERVICE – 30 DAY NOTICE IS APPRECIATED BUT NOT A REQUIREMENT TO CANCEL SERVICE.

Nassau Pools, Inc. Representative Initials _____

NASSAU POOLS, INC.

1860 J&C Boulevard
Naples, FL, 34109
License #CPC1456809

August 13, 2026

Bermuda Greens HOA

13136 Castle Harbour Dr.
Naples, FL 34110
ATTN: sara@camswfl.com

ADDITIONAL SERVICE/MAINTENANCE/REPAIR NOTES

NOTE: In addition, we have TEN full-time, in-house, licensed, and insured service technicians that can perform all repairs for your pool/spa; including pumps, motors, heaters, filters, control systems, leak detection and repairs. Our labor charge for repairs is \$175 per hour and our labor rate for special cleans in the event of pressure cleaning or hurricanes etc. are \$75 per hour.

NOTE: Phosphate treatments are **NOT** included in the price of the general cleaning. Should the city/county add phosphates to the water and treatment is required, additional fees will apply. **The minimum charge for phosphate treatment, inclusive of labor and material, is \$500.** Upon completion, the filters may need to be detergent cleaned or replaced due to the phosphate removal process. A price will be provided prior to any detergent cleaning or replacement.

NOTE: FILTERS – It is required to replace the cartridge filters in a commercial application 1X per year (some may require replacement 2x per year). D/E filters are required to be replaced 1X per year and/or detergent cleaned 2X per year. The filters are backwashed as needed, or at minimum, 2X per month. Some HOA's need/request additional detergent cleaning and we are happy to accommodate additional cleaning schedules, if requested.

NOTE: REPAIR QUOTES – if a written quote for a repair is required we are happy to provide a written quote. When a written quote is required, the minimum proposal will be \$500.

ACCEPTED BY: _____ TITLE: _____ DATE: _____

Thank you for the opportunity to assist with your swimming pool needs. If there is anything we can do to assist, please let us know. We can be reached at 239-597-2112 or via email at office@nassaupoolservice.com.

Best Regards,



Carlos Botana
Nassau Pools, Inc.

Serving SWFL Since 1955
CPC1456809

NASSAU POOLS, INC.

1860 J&C Boulevard
Naples, FL, 34109
License #CPC1456809

August 17, 2026

Bermuda Greens HOA

13136 Castle Harbour Dr.
Naples, FL 34110
ATTN: sara@camswfl.com

Please see below our service contract for monthly maintenance at Bermuda Greens noted above. The pricing is valid for 30 days from the date of the proposal. A signed contract is required to commence with a maintenance program.

Standard 3X1 Maintenance Program

1. Test pool/spa water for chlorine and adjust as necessary.
2. Test pool/spa water for pH and adjust as necessary.
3. Test pool/spa water for total alkalinity and adjust as necessary.
4. Test pool/spa water for cyanuric acid and adjust as necessary.
5. Test pool/spa water for salt content – if applicable and adjust as necessary.
6. Vacuum pool/spa – 1X per week. Additional vacuums are billed at \$75 per hour
7. Clean tiles on pool/spa- as needed to remove debris/mold/prevent algae.
8. Brush walls on pool/spa as needed to remove debris and prevent algae.
9. Net/skim surface of pool/spa as needed to remove debris.
10. Check equipment weekly and report issues for approval and repair.
11. Backwash filters as necessary.
12. Fill out HD form as required.

3x1: Items 1 through 10 include needed chemicals for the sum of \$950.00per month.

NOTE: All services will be performed under normal weather conditions. Cases of exceptional weather, (gale force winds, hurricanes, tropical storms) or pressure washing of decks or homes may cause additional expenses to owners.

NOTE: The route technician that will take care of the pool will be the same person pending illness or vacation. The route technician, along with anyone that would fill in during an absence, are licensed and insured as well as have all the accreditations required to take care of a commercial pool in Lee and Collier Counties.

NOTE: WEEKEND 911 LINE / AFTER HOURS LINE. Our weekend 911/Emergency line is available 24/7/365 by calling our main line at 239-597-2112 and following the prompts, using button 2. We have a cleaning and repair technician on call during the evenings and weekends. Our labor rate for weekend or after-hours emergency calls is \$250 per hour.

NOTE: BILLING – Invoices are sent out on the 25th of the month for the following month.

NOTE: CANCELLATION OF SERVICE – 30 DAY NOTICE IS APPRECIATED BUT NOT A REQUIREMENT TO CANCEL SERVICE.

Nassau Pools, Inc. Representative Initials _____

NASSAU POOLS, INC.

1860 J&C Boulevard
Naples, FL, 34109
License #CPC1456809

August 17, 2026

Bermuda Greens HOA

13136 Castle Harbour Dr.
Naples, FL 34110
ATTN: sara@camswfl.com

ADDITIONAL SERVICE/MAINTENANCE/REPAIR NOTES

NOTE: In addition, we have TEN full-time, in-house, licensed, and insured service technicians that can perform all repairs for your pool/spa; including pumps, motors, heaters, filters, control systems, leak detection and repairs. Our labor charge for repairs is \$175 per hour and our labor rate for special cleans in the event of pressure cleaning or hurricanes etc. are \$75 per hour.

NOTE: Phosphate treatments are **NOT** included in the price of the general cleaning. Should the city/county add phosphates to the water and treatment is required, additional fees will apply. **The minimum charge for phosphate treatment, inclusive of labor and material, is \$500.** Upon completion, the filters may need to be detergent cleaned or replaced due to the phosphate removal process. A price will be provided prior to any detergent cleaning or replacement.

NOTE: FILTERS – It is required to replace the cartridge filters in a commercial application 1X per year (some may require replacement 2x per year). D/E filters are required to be replaced 1X per year and/or detergent cleaned 2X per year. The filters are backwashed as needed, or at minimum, 2X per month. Some HOA's need/request additional detergent cleaning and we are happy to accommodate additional cleaning schedules, if requested.

NOTE: REPAIR QUOTES – if a written quote for a repair is required we are happy to provide a written quote. When a written quote is required, the minimum proposal will be \$500.

ACCEPTED BY: _____ TITLE: _____ DATE: _____

Thank you for the opportunity to assist with your swimming pool needs. If there is anything we can do to assist, please let us know. We can be reached at 239-597-2112 or via email at office@nassaupoolservice.com.

Best Regards,



Carlos Botana
Nassau Pools, Inc.

Serving SWFL Since 1955
CPC1456809



BERMUDA GREENS CONDOMINIUM ASSOCIATION

ARCHITECTURAL REVIEW COMMITTEE GUIDELINES AND PROCEDURES

APPROVED AND ADOPTED BY THE BOARD OF DIRECTORS

ORIGINAL: FEBRUARY 2015

REVISION 1: APRIL 30, 2019

REVISION 2: OCTOBER 30, 2020

REVISION 3: July 21, 2026

These Guidelines and Procedures may be amended or revised at any time by the Architectural Review Committee and Bermuda Greens Condominium Association Board of Directors

Table of Contents

Subject	Page
Mission Statement.....	2
Restatement of Paragraph 11.4 of the Bermuda Greens Declaration of Condominium.....	2
Projects Requiring ARC Review and Board of Director Approval.....	3
Changes That Are Not Permitted.....	3
Summary of Discussions with Collier County Code Office.....	4
Discussion of Specific Projects & Requirements.....	4
Contractor Requirements.....	7
Collier County Permitting.....	7
Process and Procedures for Requesting Board Approval.....	7
Attachments:	
1. Questions To Ask Before Signing a Contract	9 10
2. Photographs of Referenced Items	End

ARCHITECTURAL REVIEW COMMITTEE

MISSION STATEMENT

The Architectural Review Committee (ARC) was established by the Bermuda Greens Condominium Association Board of Directors in 2014. Its mission is to assist the elected Board of Directors in improving and maintaining the architectural quality of Bermuda Greens, preserve home equity value, maintain a safe environment, and ensure that all modifications or improvements do not jeopardize the safety and soundness of the community buildings and infrastructure.

It is further tasked with the specific responsibilities of reviewing all requests and plans submitted by owners wanting to undertake alterations, modifications and/or improvements to their individual units; to review the qualifications, licenses and insurance coverages of contractors and/or vendors that will be employed in accomplishing the planned work; and to make recommendations to the Board of Directors as to the approval or disapproval of each of the requested projects. The ARC is established as an advisory committee and has no approval authority or vote on the Board of Directors unless a member of the ARC committee is also an elected member of the Board of Directors.

RESTATEMENT OF PARAGRAPH 11.4 OF THE BERMUDA GREENS DECLARATION OF CONDOMINIUM

The following is an extract of the current declaration and is provided as a reminder to all owners contemplating any interior or exterior alteration, change, improvement, or renovation of his/her individual unit.

11.4 A l t e r a t i o n to Units and Limited Common Elements by Unit Owner. No owner shall make or cause the making of any structural modifications or alterations to his unit or its appurtenant limited common elements without first obtaining the written consent of the Association, which consent shall be denied if a majority of the Board of Directors determines that the proposed modifications or alterations might adversely affect, or in any manner be detrimental to, the Condominium in part or whole. If any unit owner requests approval of an alteration or modification involving the removal of any interior partition, the Association may permit such removal if the partition to be removed is not a load-bearing partition and so long as the removal thereof would not materially affect or interfere with the utility services constituting common elements; if any located there in. No owner shall cause his porch or lanai to be enclosed or cause any changes, structural or non-structural, to be made to the unit or building, including painting or other decorations outside of the unit, or the installation of any electrical wiring, television or radio antenna, appliance or Jacuzzi, or in any manner change the exterior appearance of any portion of the Condominium, without the prior written consent of the Board of Directors. Any glass, screen, curtain, blind, shutter, awning or other item which may be installed on any porch or lanai is subject to regulation by the Board of Directors.”

PROJECTS REQUIRING ARC REVIEW AND BOARD OF DIRECTOR APPROVAL

The following is a list of projects that require ARC review and Board of Director approval. No work is to be started until owners have received written notification that their application for said work has been approved. If there are questions concerning whether a project you are considering requires ARC approval and Board approval, contact the Property Manager at the Clubhouse before starting any work.

1. Any proposed structural change to any interior walls.
2. Any proposed work involving electrical, plumbing, air conditioning refrigerant line changes, and/or other fixture(s) or elements, including utility elements, supplied by a source outside the unit.
3. Any proposed work involving the installation and/or replacement of existing floor coverings to include wood, tile, carpeting, vinyl, etc.
4. Any proposed work involving the installation or replacement of screen/storm doors, garage doors, exterior doors, windows, sliding doors, awnings, and/or hurricane shutters.

CHANGES THAT ARE NOT PERMITTED

The following is a list of projects, changes, alterations, and modifications that are not permitted:

1. Any changes outside a unit, except for hurricane shutters that require prior approval (See above)
2. Changes to/replacement of any landscaping
3. Changes to /replacement of outside walls, walkways, driveways
4. Changes to / replacement of roof, gutter, downspouts
5. Installation of skylights or light tubes
6. Changes or alterations to parking spaces or carports
7. Changes to any other common areas or limited common areas in and/or around the exterior of buildings.

SUMMARY OF DISCUSSION WITH COLLIER COUNTY BUILDING CODE COMPLIANCE OFFICE CONCERNING WINDOWS AND DOORS

The following is a summary of a March 13, 2019, discussion between Mr. Gibbons of the Collier County Code Compliance Office and a member of the Bermuda Greens Architectural Committee concerning current building code requirements as it pertains to the installation of replacement windows and sliding glass doors. The Bermuda Greens Board of Directors used this information in developing the guidelines set forth below, recognizing that it may be necessary to change these requirements from time to time as the Collier County building and fire code requirements change.

1. All replacement windows and sliding glass doors must be hurricane impact resistant unless the opening is already protected by code compliant hurricane shutters.
2. All sleeping rooms must have a window/door that meets minimum requirements for an emergency escape and rescue (egress window) as required by the current fire code.
3. Windows facing the Gulf of Mexico, or the ocean must have “turtle glass” ---- dark glass to prevent the exfiltration of light which negatively impacts wildlife. Since Bermuda Greens is not facing ocean or Gulf, it is exempt from this requirement.
4. Both building and fire permits are required and both building, and fire code inspections are required after the work is completed to ensure compliance with applicable codes.
5. Currently the following items are left to the discretion of a community’s individual condominium board of directors as governed by the association’s Declaration, Bylaws, and established documents.
 - a. Window tinting and use of low emissive glass
 - b. Type of window casing, i.e., vinyl, aluminum
 - c. Type of window, i.e., single-hung, double-hung, or casement, etc.
 - d. Style of mullions
 - e. Insulated or non-insulated glass
 - f. Size and/or color of screens.
6. Finally, the code compliance office strongly recommended that owners deal only with local contractors who are reputable, licensed, insured, and familiar with Collier County building codes and install quality products to reduce the likelihood of problems. The ARC Committee requires these minimum standards for contractors.

DISCUSSION OF SPECIFIC PROJECT AND REQUIREMENTS

The following provides minimum requirements for the individual projects identified below:

1. **General:** All changes/improvements to a unit that can be viewed from the outside must conform to the existing shape, form, design, and style.
2. **Flooring:**
 - a. Floor soundproofing material of at least the equivalent of Proflex 90 or better must be used under all second story flooring except those areas that are carpeted.
 - b. The concrete floors of all first floor units must be water-proofed prior to the installation of any flooring.
 - c. All materials for all projects must be inspected and approved by an ARC member, Board member, and/or the property manager once delivered on site and prior to any/all installation.
 - d. When installing tile or hardwood flooring, a ¼ inch expansion space must be left between the flooring material and the wall to allow for product expansion. Expansion space may be covered with baseboard or quarter-round as desired.
3. **Windows:**
 - a. All replacement windows and their installation must meet current Collier County Building Code hurricane/impact glass requirements and specifications and must be installed according to manufacturer's guidelines to ensure proper drainage. This includes the following checklist as it pertains to second floor units:
 - The contractor should verify that all weep holes are not obstructed or blocked.
 - To ensure proper drainage, a small gap should be maintained between the window and the top of the lighter-colored painted bump-out located immediately below the window frame. (Please refer to page five at the rear of this document.)
 - Sealants, caulking and waterproofing MUST be allowed to cure and a water test performed to assure there are no leaks.
 - When stucco repairs are applied to the building to complete the window installation, incorporating an appropriate angle or slight pitch to the lighter-colored bump-out will ensure proper drainage necessary for the window weep holes to function effectively.
 - Measure and confirm the distance between the bottom of the window and the stucco bump-out, as well as the pitch grade of the light-colored bump-out.
 - Prep and touch up affected exterior body and stucco band areas with elastomeric paint.

- b. Clear glass or light grey glass tint is permitted. No other glass tints or colors permitted. Mirrored glass is not permitted.
- c. Windows frames may be vinyl or aluminum.
- d. Windows and grids must be white.
- e. Window screens must be light charcoal grey in color.
- f. Double hung windows are required in second floor units in buildings with garages. Single hung windows are not permitted in these units.
- g. Either single hung or double hung windows are permitted in all first floor units of all buildings and in second floor units in buildings which do not have garages. Only windows that open and close vertically are permitted (no casement or sliding windows).
- h. Grid patterns and designs must be identical to the original windows.
- i. Low E glass is also an option in single hung windows, arch windows and fixed windows, but only if a light grey tint is added to the glass light grey tint is to obscure the green appearance).
- j. Insulated window glass (argon gas) is an option in all windows.

4. **Sliding Glass Doors:**

- a. All replacement glass doors and their installation must meet current Collier County Building Code hurricane/impact glass requirements and specifications.
- b. Clear glass or light grey glass tint permitted. No other glass tints or colors permitted. Mirrored glass is not permitted.
- c. Sliding glass doors may be vinyl or aluminum.
- d. Sliding glass doors must be white in color.
- e. Insulated glass doors (argon gas) are an option.
- f. Low E glass is an option, but only if a light grey tint is added to the glass (to obscure the green appearance).
- g. No grids are permitted on sliding glass doors.

5. **Hurricane / Storm Shutters & Storm Screens:**

- a. All storm shutters and storm screens on windows and lanais must be reviewed by the ARC and approved by the Board of Directors **BEFORE** installation.
- b. All shutters and screens and their installation must meet current Collier County Building Code hurricane protection requirements and specifications.
- c. Shutters and frame must be White in color.
- d. Storm shutters and storm screens on the lanai are to be mounted on the inside of the existing screen. A board exclusion is made for units built with no lanai.
- e. **No channel or other barricade designed to secure the bottom of any shutter, panel, awning, etc. is permitted to be installed on the lanai floor which could function as a dam thereby restricting the amount of any water entering or accumulating on the lanai floor.**

6. Garage Doors:

- a. Garage doors must be hurricane rated and must meet current Collier County and building code requirements as specified.
- b. The replacement door must match the original doors in design and style.
- c. The top section of the door must have a Sunray 4 light Polycarbonate window.
- d. The door must be White in color.
- e. Attached at the end of this document on Page 13, is a photograph of an Amarr Stratford 1000, Colonial Panel garage door which is an acceptable replacement.

7. Entry Doors & Storm/Screen Doors:

- a. Entry doors to all units must be steel exterior grade with four vertical panels similar in style and color to all other existing entry doors. No glass is allowed in any part of the entry door itself.
- b. Storm and screen doors installed at the front entry doorway must be full view glass doors with full screen or self-storing screens.
- c. Entry storm/screen doors must be White in color.
- d. Hardware may be Nickel or Brass in color.
- e. Attached to this document on Page 13 are photographs of acceptable entry and storm doors models.

8. Lanai Screen and Frames:

- a. Lanai screening will be Charcoal in color.
- b. Frames are to be White in color.
- c. The bottom channel of frame will have weep holes a minimum of 3/8" drilled/installed a minimum of three in every screened panel to allow water on the lanai floor egress to the outside.
- d. When replacing existing lanai screen frames, aluminum flashing material must be installed under the frame on the outer edge of second floor lanai floors to redirect water beyond the edge of the lanai floor and away from the building structure.

COLLIER COUNTY PERMITTING

No work will be undertaken within the Bermuda Greens community without a Collier County permit if said work requires such a permit. When required, Collier County code compliance permits will be obtained and posted in a visible area when work is underway.

CONTRACTOR REQUIREMENTS

1. Any company, vendor, contractor, or other entity engaged to perform work in any unit must provide the property management office with proof of all legally required licenses, insurance, and other documents.
2. All contractors must carry a minimum of \$2M of General Liability Insurance in total, with \$1M coverage per occurrence.
3. All contractors must also provide proof of auto insurance and Workers Compensation insurance coverage.
4. All contractors must have proof of Florida State Certification for Competency of Trade, if necessary.
5. All contractors must have owner permission, and the owner is required to register their contractor with the property manager of Bermuda Greens whenever entering Bermuda Greens property.
6. Work will be conducted only within the hours and days permitted by Association Policies, which is Monday through Saturday from 8:00 AM to 5:00 PM and there will be no excessive noise that would be offensive to other residents in the Bermuda Greens community.

PROCESS AND PROCEDURES FOR REQUESTING BOARD APPROVAL

The following outlines the application, review, approval, and follow-up process. Each qualifying individual project requires a separate application. **In cases of an emergency, the advance submission of an ARC application is temporarily waived, but immediately after the emergency portion of the repair is addressed, the ARC paperwork must be submitted with an explanation of the reason for the emergency circumstances.**

- **Step 1:** Owner completes the Bermuda Greens Architectural Change Application form and with all relevant attachments/enclosures, including sketches, detailed drawings with measurements, architectural plans, pictures, brochures, and sample materials, etc. and sends it to the Property Manager at least thirty calendar days before work is to begin.
- **Step 2:** Property manager logs in application, reviews it to ensure administrative correctness and send the application and all attachments to ARC for their review. Incomplete applications will be returned to the owner for correction and/or missing critical information.
 - **Step 3:** The ARC will review all materials, evaluate compliance with the local building codes, and confirm all contractor's licenses and/or Certifications. The ARC may also ask for additional information or clarification as needed. Upon completing its review, the ARC will send its advisory recommendations back to the Property Manager no later than fourteen calendar days after receipt from the Property Manager.
- **Step 4:** Property Manager sends application to Board for Approval/Disapproval. The board approves / disapproves, signs off, and in turn, returns the application to Property Manager.

- **Step 5:** Property Manager makes a copy of the completed application with required approval / disapprovals for Association files and sends a copy to the owner no later than five business days after receipt from the Board. Disapproval will be accompanied by an explanation as to why the project was disapproved.
- **Step 6:** Prior to the start of the approved project, the owner will contact the property manager and advise him/her of the date when all materials for the project are scheduled to be delivered and when work is scheduled to begin. Subsequently, the property manager will advise all Board Members and ARC members of the date of the scheduled delivery of materials and commencement of work.
- **Step 7:** Prior to the start of any work, an ARC member, a Board member, or the property manager will make an on-site inspection of the worksite, examine all the material/equipment staged for installation, and confirm that the materials/equipment to be installed conform with the approved application. Additionally, the project is subject to periodic inspections by the ARC, Board member, and/or property manager while it is underway.
- **Step 8:** No later than five business days after the project is completed, the owner will notify the property manager.
- **Step 9:** Property manager logs in “Project Completed” and advises Board/ARC committee.
- **Step 10:** Board/ARC committee/property manager conducts follow-up inspection to ensure project was completed according to approved application.

Attachments:

1. Questions You Should Ask Before Signing a Contract
2. Photographs of Referenced Items

Questions You Should Ask Before Signing a Contract

Licenses

- Is the contractor licensed in the category of work you are requesting?
- Verify that the license is still current and in good standing.
- Verify that the holder of the license legally qualifies the company you are hiring.

Insurance

- Does the contractor have liability and workers compensation insurance?

Experience

- Does the contractor have at least 5 years of experience replacing windows and doors in South Florida or any other type of work you plan to undertake?

Installation

- Ask if all the contractor's installers are employees or subcontractors.
- If they use subcontractors, be sure to get proof that the subcontractors are all licensed and fully insured.
- Be sure you hire them to complete the installation so that you will not need someone else to finish any details such as stucco or drywall repair.
- Be sure that the window replacement will include replacement of any rotted wood.
- Find out their policy about replacement of broken windowsills.

References

- Can the contractor provide the name, phone number, and addresses of their most recent past customers? References from a window installation company will show the type of work and customer service they provide.
- Does the contractor's written contract detail every aspect of the installation?
- Be sure to check that the contractor's license number is printed on the contract that you are asked to sign.
- Make sure the installation contract explains when payments are due.

Other Important Topics of Discussion for Your Installation Professional

- Check to see if the contractor is an authorized dealer for the products that are to be installed.
- Be sure that everything is done with a permit.
- How much does the contractor charge for permitting?
- Verify the name of the contractor you hired is the same as the contractor named on the permit.
- When the installation is completed be sure that the contractor will schedule the final permit inspection with the county.
- Before you sign a contract verify the warranties on both the products and the installation work.
- Be sure to find out how long the warranties will continue to be in effect.
- It is best to find a contractor that will also service the products they install.
- How long has the contractor been in business?
- Be sure that there is a written contract that outlines all the details of the work to be done.



Eastern Architectural Systems Double Hung Vinyl Insulated Impact Windows w/ Light Gray Tint


Note about screens that come with Eastern Windows: Single-hung windows come with half screens that cover only the bottom sash. Double-hung windows come with full screens that cover both upper and lower sashes. The screens for both styles of window can be removed for cleaning but neither one slides up and down.

The photo below shows the installation of this second-floor window done **incorrectly**. Please note that the light-colored bump-out is positioned directly against the window frame, which obstructs the weep holes necessary for proper water drainage.



The photo below illustrates the proper method for installing a second-floor window. Observe the gap between the window and the light-colored bump-out, which facilitates effective drainage of water through the weep holes in the window.






Entry & Full View Storm Door with no Screen



Self-Storing Storm Door with Screen in Place



**Full View Storm Door with Screen
Stored**



Amarr Stratford Garage Door

ID	Latitude	Longitude	Asset	Type	Severity	Old Fix
71	26.291605	-81.782773	Roadway	Void	1	No
75	26.291552	-81.782768	Roadway	Void	1	No
80	26.291529	-81.782700	Driveway	Void	1	No
82	26.291527	-81.782709	Driveway	Void	1	No
89	26.291490	-81.782704	Driveway	Void	1	No
94	26.291463	-81.782732	Driveway	Void	1	No
96	26.291314	-81.782778	Roadway	Void	1	Yes Bad
110	26.291259	-81.782746	Roadway	Void	1	No
116	26.291225	-81.782747	Roadway	Void	1	No
118	26.291224	-81.782804	Roadway	Void	1	No
119	26.291215	-81.782813	Roadway	Void	1	No
120	26.291187	-81.782774	Roadway	Void	1	No
121	26.291140	-81.782762	Driveway	Void	1	No
124	26.291125	-81.782770	Roadway	Void	1	No
126	26.291106	-81.782780	Roadway	Void	1	No
132	26.291085	-81.782859	Roadway	Void	1	No
133	26.291140	-81.782765	Roadway	Void	1	No
140	26.291110	-81.782786	Roadway	Void	1	No
141	26.291088	-81.782789	Roadway	Void	1	No
145	26.290937	-81.782885	Roadway	Void	1	No
153	26.290798	-81.782907	Roadway	Void	1	No
162	26.290790	-81.782851	Roadway	Void	1	No
167	26.290674	-81.782853	Driveway	Ridge	1	No
171	26.291821	-81.782751	Roadway	Void	1	No
180	26.290462	-81.783215	Gutter	Void	1	No
182	26.290429	-81.783330	Roadway	Void	1	No
183	26.290429	-81.783330	Roadway	Ridge	1	No
185	26.290356	-81.783443	Roadway	Void	1	No
187	26.290270	-81.783614	Roadway	Void	1	No
188	26.290227	-81.783593	Roadway	Ridge	1	No
190	26.290299	-81.783401	Roadway	Crack	1	No
191	26.290323	-81.783338	Roadway	Void	1	No
211	26.290344	-81.783006	Driveway	Void	1	No
213	26.290328	-81.783067	Driveway	Void	1	No
252	26.289789	-81.782921	Driveway	Void	1	No
254	26.289788	-81.782946	Driveway	Void	1	No
265	26.289695	-81.782956	Driveway	Void	1	No
268	26.289638	-81.782901	Driveway	Void	1	No
270	26.289671	-81.782937	Roadway	Void	1	No
277	26.289588	-81.783007	Driveway	Void	1	No
284	26.289497	-81.783051	Driveway	Void	1	No
290	26.289356	-81.783072	Driveway	Ridge	1	No
299	26.288357	-81.783417	Driveway	Void	1	No
305	26.288892	-81.783309	Driveway	Void	1	No
316	26.288407	-81.783414	Roadway	Void	1	Yes Bad
326	26.288205	-81.783473	Driveway	Ridge	1	No
334	26.288018	-81.783517	Sidewalk	Void	1	No
341	26.287980	-81.783584	Driveway	Ridge	1	No
347	26.288051	-81.783688	Driveway	Void	1	No
354	26.288044	-81.783790	Driveway	Void	1	No

356	26.288022	-81.783935	Roadway	Void	1	Yes Bad
357	26.288042	-81.783999	Roadway	Void	1	Yes Bad
361	26.288038	-81.783978	Roadway	Void	1	No
365	26.288051	-81.784077	Driveway	Void	1	Yes Bad
367	26.288062	-81.784168	Driveway	Void	1	No
371	26.288057	-81.784247	Driveway	Void	1	No
373	26.288059	-81.784295	Sidewalk	Void	1	No
374	26.288060	-81.784310	Roadway	Void	1	No
375	26.288056	-81.784320	Sidewalk	Void	1	No
376	26.288045	-81.784387	Gutter	Void	1	No
401	26.288631	-81.785395	Driveway	Void	1	No
406	26.289166	-81.785281	Roadway	Void	1	No
408	26.289275	-81.785290	Driveway	Void	1	No
411	26.289654	-81.784740	Roadway	Void	1	No
412	26.289678	-81.784740	Roadway	Void	1	No
413	26.289678	-81.784740	Roadway	Crack	1	No
414	26.289666	-81.784746	Roadway	Void	1	No
415	26.289666	-81.784746	Roadway	Ridge	1	No
416	26.289690	-81.784735	Roadway	Crack	1	No
418	26.289702	-81.784729	Driveway	Void	1	No
425	26.289802	-81.784649	Roadway	Void	1	No
431	26.289838	-81.784612	Roadway	Void	1	No
434	26.289839	-81.784613	Roadway	Void	1	No
435	26.289878	-81.784581	Roadway	Void	1	No
436	26.289871	-81.784574	Roadway	Void	1	No
445	26.290078	-81.784405	Driveway	Crack	1	No
450	26.290144	-81.783831	Roadway	Void	1	No
451	26.290125	-81.783942	Roadway	Ridge	1	No
452	26.290098	-81.784031	Roadway	Void	1	No
458	26.290127	-81.784275	Roadway	Void	1	No
461	26.290101	-81.784144	Roadway	Void	1	No
467	26.289894	-81.783957	Sidewalk	Ridge	1	No
471	26.289976	-81.783626	Sidewalk	Ridge	1	Yes Bad
476	26.289924	-81.783868	Sidewalk	Ridge	1	No
477	26.289915	-81.783941	Sidewalk	Ridge	1	No
497	26.290138	-81.783655	Guest Parking	Void	1	No
498	26.290143	-81.783677	Guest Parking	Void	1	No
501	26.290105	-81.783730	O Lot	Void	1	No
502	26.290136	-81.783749	O Lot	Void	1	No
506	26.290131	-81.783786	O Lot	Void	1	
508	26.290103	-81.783800	O Lot	Void	1	
511	26.290033	-81.783960	O Lot	Void	1	No
520	26.290037	-81.783781	O Lot	Void	1	No
528	26.290085	-81.783758	O Lot	Void	1	No
531	26.290093	-81.783732	O Lot	Ridge	1	No
532	26.290040	-81.783704	O Lot	Void	1	No
535	26.290101	-81.783694	O Lot	Ridge	1	No
541	26.290112	-81.783637	O Lot	Void	1	No
543	26.290097	-81.783615	O Lot	Void	1	No
546	26.290083	-81.783588	O Lot	Void	1	No
547	26.290083	-81.783588	O Lot	Ridge	1	No
548	26.290083	-81.783588	O Lot	Crack	1	No

549	26.290115	-81.783567	O Lot	Void	1	No
550	26.290117	-81.783566	O Lot	Ridge	1	No
568	26.289877	-81.784458	Roadway	Ridge	1	No
573	26.289869	-81.784506	Roadway	Void	1	No
588	26.289680	-81.784692	Roadway	Ridge	1	No
615	26.288914	-81.785300	Roadway	Void	1	No
667	26.289772	-81.783064	Roadway	Void	1	No
670	26.289843	-81.783043	Roadway	Void	1	No
693	26.288160	-81.784103	Guest Parking	Void	1	No
700	26.288180	-81.784345	Guest Parking	Void	1	No
712	26.288589	-81.783541	Guest Parking	Ridge	1	No
713	26.288582	-81.783533	Guest Parking	Ridge	1	No
714	26.288478	-81.783541	Car Port	Ridge	1	No
715	26.288477	-81.783501	Car Port	Ridge	1	No
716	26.288453	-81.783544	Car Port	Ridge	1	No
723	26.288316	-81.783522	Guest Parking	Void	1	No
726	26.288995	-81.783505	Sidewalk	Ridge	1	No
732	26.288817	-81.783450	Guest Parking	Ridge	1	No
746	26.289292	-81.783218	Guest Parking	Void	1	No
752	26.289331	-81.783162	Guest Parking	Ridge	1	Yes Bad
768	26.289715	-81.783135	Guest Parking	Ridge	1	No
770	26.289740	-81.783135	Guest Parking	Void	1	No
776	26.289787	-81.783120	Guest Parking	Ridge	1	No
782	26.289897	-81.783087	Guest Parking	Ridge	1	No
783	26.289897	-81.783087	Guest Parking	Void	1	No
786	26.289950	-81.783067	Guest Parking	Void	1	No
791	26.291814	-81.782752	Roadway	Iron Oxide	1	No
797	26.289698	-81.783028	Roadway	Iron Oxide	1	No
798	26.289503	-81.783052	Roadway	Iron Oxide	1	No
799	26.289387	-81.783065	Roadway	Iron Oxide	1	No
803	26.288044	-81.783746	Roadway	Iron Oxide	1	No
804	26.288091	-81.784222	Roadway	Iron Oxide	1	No
805	26.290056	-81.783001	Gutter	Gutter Depth	1	No
806	26.289968	-81.782989	Gutter	Gutter Depth	1	No
807	26.288189	-81.783973	Sidewalk	Crack	1	Yes Bad
2	26.291697	-81.783236	Driveway	Crack	2	No
4	26.291791	-81.782820	Driveway	Void	2	No
13	26.291842	-81.782480	Driveway	Ridge	2	No
30	26.291907	-81.782548	Driveway	Void	2	No
39	26.291939	-81.782654	Driveway	Void	2	No
53	26.291876	-81.782602	Roadway	Void	2	No
55	26.291830	-81.782567	Roadway	Void	2	No
66	26.291648	-81.782682	Driveway	Void	2	No
67	26.291648	-81.782682	Driveway	Void	2	No
81	26.291562	-81.782689	Driveway	Void	2	No
90	26.291490	-81.782704	Driveway	Void	2	No
91	26.291917	-81.782704	Driveway	Crack	2	No
92	26.291917	-81.782704	Driveway	Void	2	No
93	26.291463	-81.782717	Driveway	Crack	2	No
95	26.291351	-81.782778	Roadway	Void	2	No
98	26.291365	-81.782760	Roadway	Void	2	No
103	26.291348	-81.782704	Driveway	Crack	2	No

104	26.291348	-81.782704	Driveway	Void	2	No
111	26.291260	-81.782724	Driveway	Void	2	No
115	26.291224	-81.782725	Driveway	Crack	2	No
131	26.291122	-81.782829	Roadway	Void	2	No
146	26.290945	-81.782875	Roadway	Void	2	No
150	26.290912	-81.782822	Roadway	Void	2	No
152	26.290846	-81.782898	Roadway	Void	2	No
168	26.290691	-81.782814	Driveway	Void	2	No
175	26.290503	-81.783094	Roadway	Void	2	No
206	26.290391	-81.782914	Driveway	Void	2	No
236	26.290058	-81.782895	Mailbox Sidewalk	Ridge	2	No
237	26.290056	-81.782923	Driveway	Void	2	No
240	26.290014	-81.783130	Driveway	Ridge	2	No
241	26.290036	-81.782873	Driveway	Crack	2	No
242	26.290029	-81.782911	Driveway	Void	2	No
245	26.290023	-81.782962	Driveway	Void	2	No
253	26.289788	-81.782946	Driveway	Void	2	No
256	26.289802	-81.782996	Driveway	Ridge	2	No
259	26.289763	-81.782931	Driveway	Void	2	No
261	26.289744	-81.783038	Driveway	Void	2	No
262	26.289695	-81.782901	Driveway	Void	2	No
266	26.289701	-81.782982	Driveway	Void	2	No
271	26.289676	-81.782955	Driveway	Void	2	No
276	26.289590	-81.782980	Driveway	Crack	2	No
281	26.289550	-81.783028	Roadway	Void	2	No
288	26.289484	-81.782975	Driveway	Void	2	No
289	26.289468	-81.782990	Driveway	Void	2	No
291	26.289424	-81.783083	Driveway	Crack	2	No
292	26.289368	-81.782980	Driveway	Void	2	No
301	26.288222	-81.783436	Driveway	Ridge	2	No
306	26.288841	-81.783306	Driveway	Void	2	No
309	26.288717	-81.783343	Driveway	Void	2	No
319	26.288340	-81.783387	Driveway	Void	2	No
322	26.288311	-81.783422	Driveway	Crack	2	No
324	26.288228	-81.783413	Driveway	Void	2	No
327	26.288148	-81.783470	Driveway	Void	2	No
328	26.288148	-81.783470	Driveway	Void	2	No
329	26.288130	-81.783453	Driveway	Void	2	No
330	26.288111	-81.783493	Driveway	Void	2	No
332	26.288117	-81.783535	Driveway	Crack	2	No
333	26.287985	-81.783533	Driveway	Crack	2	No
335	26.288048	-81.783502	Driveway	Void	2	No
336	26.288023	-81.783638	Driveway	Void	2	No
338	26.288054	-81.783616	Driveway	Crack	2	No
339	26.287990	-81.783584	Driveway	Void	2	No
342	26.287980	-81.783584	Driveway	Void	2	No
350	26.288046	-81.783710	Driveway	Void	2	No
360	26.292144	-81.782709	Driveway	Void	2	No
372	26.288057	-81.784247	Driveway	Crack	2	No
390	26.288359	-81.785636	Driveway	Void	2	No
392	26.288429	-81.785389	Roadway	Ridge	2	No
397	26.288558	-81.785378	Gutter	Void	2	No

399	26.288617	-81.785396	Driveway	Void	2	No
400	26.288620	-81.785421	Driveway	Void	2	No
426	26.289799	-81.784641	Roadway	Cosmetic	2	No
441	26.289893	-81.784556	Roadway	Crack	2	No
448	26.290167	-81.783768	Roadway	Void	2	No
453	26.290080	-81.784110	Roadway	Void	2	No
460	26.290114	-81.784146	Roadway	Void	2	No
466	26.290270	-81.783645	Roadway	Ridge	2	No
470	26.290016	-81.783515	Sidewalk	Ridge	2	No
486	26.290023	-81.783580	Car Port	Void	2	No
487	26.290041	-81.783575	Guest Parking	Ridge	2	No
490	26.290077	-81.783508	Guest Parking	Ridge	2	No
494	26.290160	-81.783580	Guest Parking	Ridge	2	No
500	26.290135	-81.783706	Guest Parking	Void	2	
512	26.290033	-81.783960	O Lot	Crack	2	No
515	26.290040	-81.783913	O Lot	Void	2	No
533	26.290061	-81.783683	O Lot	Void	2	No
534	26.290061	-81.783683	O Lot	Crack	2	No
536	26.290083	-81.783693	O Lot	Void	2	No
539	26.290065	-81.783626	O Lot	Void	2	No
542	26.290110	-81.783642	O Lot	Ridge	2	No
544	26.290095	-81.783641	O Lot	Crack	2	No
576	26.289850	-81.784532	Roadway	Void	2	No
578	26.289834	-81.784571	Roadway	Void	2	No
579	26.289819	-81.784547	Roadway	Void	2	No
582	26.289798	-81.784591	Roadway	Void	2	No
584	26.289740	-81.784604	Roadway	Void	2	No
586	26.289724	-81.784659	Roadway	Void	2	No
589	26.289680	-81.784692	Roadway	Void	2	No
602	26.289686	-81.784620	Guest Parking	Void	2	No
605	26.289749	-81.784588	Car Port	Void	2	No
613	26.289160	-81.785269	Roadway	Ridge	2	No
630	26.289352	-81.785012	Guest Parking	Void	2	No
636	26.289075	-81.785189	Car Port	Ridge	2	No
642	26.288979	-81.785246	Guest Parking	Void	2	No
646	26.288736	-81.785250	Guest Parking	Ridge	2	No
651	26.288068	-81.783829	Roadway	Void	2	No
655	26.288112	-81.783603	Roadway	Void	2	No
658	26.288199	-81.783528	Roadway	Crack	2	No
663	26.289557	-81.783082	Roadway	Void	2	No
665	26.289701	-81.783065	Roadway	Void	2	No
668	26.289772	-81.783064	Roadway	Crack	2	No
676	26.288222	-81.784346	Sidewalk	Ridge	2	No
682	26.288163	-81.784108	Sidewalk	Ridge	2	No
691	26.288136	-81.783982	Car Port	Ridge	2	No
694	26.288145	-81.784112	Guest Parking	Void	2	No
705	26.288599	-81.783563	Sidewalk	Ridge	2	No
724	26.288312	-81.783542	Guest Parking	Void	2	No
727	26.288975	-81.783495	Sidewalk	Ridge	2	No
734	26.288835	-81.783445	Guest Parking	Void	2	No
745	26.289229	-81.783271	Guest Parking	Ridge	2	No
772	26.289748	-81.783132	Guest Parking	Ridge	2	No

779	26.289852	-81.783089	Guest Parking	Ridge	2	No
789	26.292285	-81.782766	Roadway	Iron Oxide	2	No
790	26.291909	-81.782763	Roadway	Iron Oxide	2	No
792	26.291805	-81.782954	Roadway	Iron Oxide	2	No
793	26.291710	-81.783162	Roadway	Iron Oxide	2	No
794	26.291669	-81.783174	Roadway	Iron Oxide	2	No
795	26.290225	-81.783058	Roadway	Iron Oxide	2	No
796	26.289813	-81.783009	Roadway	Iron Oxide	2	No
801	26.288552	-81.783457	Roadway	Iron Oxide	2	No
802	26.288444	-81.783434	Roadway	Iron Oxide	2	No
1	26.291714	-81.783240	Driveway	Void	3	No
3	26.291868	-81.782948	Driveway	Void	3	No
6	26.281380	-81.783081	Driveway	Crack	3	Yes Bad
8	26.291910	-81.783020	Sidewalk	Crack	3	No
11	26.291842	-81.782652	Driveway	Crack	3	No
12	26.292150	-81.782738	Driveway	Crack	3	No
15	26.291765	-81.782652	Driveway	Crack	3	No
16	26.291727	-81.783295	Sidewalk	Ridge	3	No
19	26.292338	-81.782769	Driveway	Void	3	No
21	26.292113	-81.782883	Driveway	Void	3	No
27	26.291921	-81.782525	Driveway	Crack	3	No
31	26.291945	-81.782591	Driveway	Void	3	No
33	26.291978	-81.782525	Driveway	Ridge	3	No
36	26.291862	-81.782826	Driveway	Crack	3	No
37	26.291862	-81.782826	Driveway	Void	3	No
38	26.291785	-81.782783	Driveway	Crack	3	No
41	26.291939	-81.782654	Driveway	Void	3	No
42	26.291978	-81.782654	Driveway	Void	3	No
43	26.291978	-81.782654	Driveway	Crack	3	No
52	26.291804	-81.782673	Driveway	Void	3	No
56	26.291759	-81.782711	Guest Parking	Crack	3	No
58	26.291683	-81.782762	Roadway	Void	3	No
62	26.291694	-81.782721	Driveway	Void	3	No
68	26.291561	-81.782725	Driveway	Void	3	No
70	26.291561	-81.782725	Roadway	Void	3	Yes Bad
76	26.291494	-81.782714	Driveway	Void	3	No
87	26.291494	-81.782702	Driveway	Void	3	No
100	26.291348	-81.782739	Driveway	Void	3	No
101	26.291348	-81.782739	Driveway	Crack	3	No
105	26.291343	-81.782732	Roadway	Ridge	3	No
107	26.291942	-81.782724	Roadway	Crack	3	No
108	26.291263	-81.782797	Roadway	Void	3	No
109	26.291259	-81.782789	Roadway	Crack	3	No
112	26.291260	-81.782724	Driveway	Crack	3	No
113	26.291261	-81.782686	Driveway	Crack	3	No
114	26.291229	-81.782706	Driveway	Void	3	No
122	26.291127	-81.782738	Driveway	Void	3	No
125	26.291115	-81.782736	Driveway	Void	3	No
127	26.291083	-81.782781	Driveway	Crack	3	No
134	26.291035	-81.782757	Driveway	Crack	3	No
135	26.291022	-81.782747	Driveway	Void	3	No
137	26.291134	-81.782758	Driveway	Void	3	No

144	26.291006	-81.782818	Roadway	Void	3	No
147	26.290945	-81.782819	Roadway	Void	3	No
149	26.290859	-81.782755	Sidewalk	Ridge	3	No
151	26.290874	-81.782828	Roadway	Void	3	No
154	26.290787	-81.782895	Roadway	Void	3	No
157	26.290820	-81.782808	Driveway	Void	3	No
161	26.290800	-81.782808	Driveway	Crack	3	No
163	26.290792	-81.782907	Roadway	Void	3	No
165	26.290712	-81.782794	Driveway	Crack	3	No
166	26.290713	-81.782778	Driveway	Crack	3	No
169	26.290691	-81.782814	Driveway	Crack	3	No
170	26.290633	-81.782769	Sidewalk	Crack	3	No
172	26.291806	-81.782759	Roadway	Void	3	No
176	26.290556	-81.782997	Roadway	Void	3	No
178	26.290479	-81.783166	Roadway	Void	3	No
179	26.290443	-81.783172	Roadway	Ridge	3	No
184	26.290356	-81.783443	Roadway	Void	3	No
192	26.290329	-81.783331	Roadway	Crack	3	No
194	26.290439	-81.783135	Driveway	Void	3	No
197	26.290530	-81.782960	Driveway	Void	3	No
199	26.290482	-81.782918	Driveway	Void	3	No
204	26.290366	-81.783039	Driveway	Crack	3	No
207	26.290366	-81.782912	Driveway	Void	3	No
210	26.290328	-81.783067	Sidewalk	Crack	3	No
214	26.290206	-81.782857	Driveway	Void	3	No
216	26.290240	-81.782945	Driveway	Crack	3	No
217	26.290319	-81.783019	Driveway	Void	3	No
221	26.290260	-81.782990	Driveway	Void	3	No
225	26.290237	-81.782881	Driveway	Crack	3	No
229	26.290173	-81.782970	Driveway	Void	3	No
232	26.290172	-81.783007	Driveway	Ridge	3	No
234	26.290155	-81.782988	Driveway	Void	3	No
243	26.290029	-81.782911	Driveway	Void	3	No
248	26.289967	-81.782982	Driveway	Crack	3	No
249	26.289967	-81.782982	Driveway	Void	3	No
255	26.289793	-81.782986	Driveway	Crack	3	No
269	26.289657	-81.782899	Driveway	Void	3	No
272	26.289678	-81.782980	Driveway	Void	3	No
273	26.289682	-81.783015	Driveway	Void	3	No
274	26.289674	-81.783031	Driveway	Void	3	No
278	26.289602	-81.783020	Driveway	Crack	3	No
279	26.289602	-81.783020	Roadway	Void	3	No
280	26.289556	-81.782985	Roadway	Crack	3	No
282	26.289550	-81.783028	Driveway	Void	3	No
285	26.289508	-81.783072	Driveway	Void	3	No
294	26.288622	-81.783342	Driveway	Void	3	No
295	26.288604	-81.783365	Driveway	Void	3	No
297	26.288589	-81.783389	Driveway	Ridge	3	No
298	26.288434	-81.783373	Driveway	Void	3	No
302	26.288913	-81.783308	Driveway	Void	3	No
307	26.288811	-81.783300	Driveway	Void	3	No
310	26.288696	-81.783330	Driveway	Void	3	No

312	26.288612	-81.783381	Driveway	Crack	3	No
315	26.288407	-81.783414	Driveway	Void	3	No
317	26.288379	-81.783431	Driveway	Void	3	No
321	26.288278	-81.783423	Driveway	Void	3	No
325	26.288217	-81.783453	Driveway	Void	3	No
331	26.288116	-81.783520	Driveway	Crack	3	No
337	26.288054	-81.783616	Driveway	Crack	3	No
340	26.287980	-81.783584	Driveway	Crack	3	No
343	26.287958	-81.783592	Driveway	Crack	3	No
344	26.287958	-81.783592	Roadway	Void	3	No
346	26.288092	-81.783691	Driveway	Void	3	No
348	26.288044	-81.783742	Driveway	Void	3	No
351	26.288032	-81.783739	Driveway	Crack	3	No
352	26.288061	-81.783777	Driveway	Void	3	No
363	26.288016	-81.783974	Driveway	Void	3	No
366	26.288051	-81.784077	Driveway	Crack	3	No
378	26.288279	-81.785194	Driveway	Void	3	No
383	26.288330	-81.785367	Roadway	Crack	3	No
384	26.288338	-81.785380	Roadway	Void	3	No
388	26.288338	-81.785426	Driveway	Void	3	No
396	26.288494	-81.785417	Driveway	Void	3	No
398	26.288572	-81.785382	Driveway	Crack	3	No
405	26.289054	-81.785278	Roadway	Void	3	No
407	26.289149	-81.785281	Roadway	Void	3	No
417	26.289683	-81.784738	Roadway	Void	3	No
419	26.289726	-81.784700	Roadway	Crack	3	No
420	26.289745	-81.784716	Driveway	Void	3	No
421	26.289745	-81.784716	Driveway	Crack	3	No
422	26.289716	-81.784689	Roadway	Void	3	No
423	26.289716	-81.784689	Roadway	Crack	3	No
424	26.289786	-81.784654	Roadway	Crack	3	No
427	26.289836	-81.784612	Sidewalk	Crack	3	No
428	26.289836	-81.784612	Sidewalk	Ridge	3	No
429	26.289836	-81.784601	Roadway	Void	3	No
430	26.289836	-81.784601	Roadway	Crack	3	No
433	26.289855	-81.784606	Roadway	Void	3	No
437	26.289878	-81.784581	Roadway	Crack	3	No
440	26.289913	-81.784544	Roadway	Void	3	Yes Bad
447	26.290133	-81.783956	Roadway	Void	3	No
454	26.290276	-81.784376	Roadway	Void	3	No
455	26.290249	-81.784336	Roadway	Void	3	No
459	26.290109	-81.784119	Gutter	Void	3	No
462	26.290128	-81.784010	Roadway	Void	3	No
468	26.289988	-81.783951	Sidewalk	Ridge	3	No
469	26.289961	-81.783954	Sidewalk	Ridge	3	No
474	26.289903	-81.783822	Patio	Crack	3	No
479	26.289960	-81.783924	Handicapped Parking	Void	3	No
482	26.290019	-81.783805	Car Port	Void	3	No
489	26.290041	-81.783534	Guest Parking	Void	3	No
492	26.290066	-81.783466	Guest Parking	Ridge	3	No
495	26.290152	-81.783604	Guest Parking	Ridge	3	No
499	26.290142	-81.783687	Guest Parking	Ridge	3	No

503	26.290120	-81.783740	O Lot	Void	3	No
504	26.290147	-81.783780	O Lot	Ridge	3	No
507	26.290118	-81.783787	O Lot	Void	3	
509	26.290103	-81.783800	O Lot	Crack	3	
510	26.290028	-81.783966	O Lot	Crack	3	No
513	26.290006	-81.783908	O Lot	Void	3	No
514	26.290006	-81.783908	O Lot	Crack	3	No
516	26.290040	-81.783913	O Lot	Crack	3	No
517	26.290019	-81.783803	O Lot	Void	3	No
518	26.290019	-81.783803	O Lot	Crack	3	No
519	26.290056	-81.783823	O Lot	Crack	3	No
521	26.290037	-81.783781	O Lot	Crack	3	No
524	26.290082	-81.783775	O Lot	Ridge	3	No
530	26.290078	-81.783754	O Lot	Crack	3	No
537	26.290083	-81.783693	O Lot	Crack	3	No
538	26.290065	-81.783657	O Lot	Ridge	3	No
540	26.290065	-81.783626	O Lot	Crack	3	No
545	26.290112	-81.783634	O Lot	Void	3	No
555	26.290097	-81.783490	O Lot	Ridge	3	No
556	26.290133	-81.783500	O Lot	Ridge	3	No
557	26.290049	-81.784383	Roadway	Void	3	No
563	26.289932	-81.784415	Roadway	Crack	3	No
564	26.289919	-81.784423	Roadway	Void	3	No
569	26.289731	-81.784532	Sidewalk	Ridge	3	No
574	26.289865	-81.784521	Roadway	Void	3	No
577	26.289826	-81.784555	Roadway	Void	3	No
581	26.289798	-81.784591	Roadway	Crack	3	No
583	26.289801	-81.784602	Roadway	Void	3	No
585	26.289739	-81.784630	Roadway	Void	3	No
587	26.289715	-81.784664	Roadway	Crack	3	No
590	26.289659	-81.784704	Roadway	Ridge	3	No
592	26.289532	-81.784762	Roadway	Void	3	No
593	26.289572	-81.784779	Car Port	Crack	3	No
594	26.289595	-81.784738	Car Port	Crack	3	No
596	26.289629	-81.784713	Car Port	Crack	3	No
599	26.289674	-81.784667	Car Port	Ridge	3	No
604	26.289728	-81.784602	Guest Parking	Ridge	3	No
611	26.289861	-81.784477	Guest Parking	Ridge	3	No
614	26.289166	-81.785260	Roadway	Void	3	No
617	26.288544	-81.785323	Roadway	Void	3	No
619	26.289272	-81.785006	Sidewalk	Ridge	3	No
622	26.289426	-81.784836	Guest Parking	Crack	3	No
623	26.289426	-81.784836	Guest Parking	Void	3	No
628	26.289371	-81.784952	Car Port	Void	3	No
629	26.289366	-81.784970	Car Port	Void	3	No
631	26.289336	-81.785048	Guest Parking	Void	3	No
635	26.289127	-81.785227	Car Port	Void	3	No
644	26.288951	-81.785233	Guest Parking	Void	3	No
647	26.288663	-81.785285	Car Port	Void	3	No
649	26.288495	-81.785278	Guest Parking	Void	3	No
650	26.288120	-81.784181	Roadway	Void	3	No
653	26.288080	-81.783832	Roadway	Void	3	No

654	26.288073	-81.783722	Roadway	Ridge	3	No
657	26.288192	-81.783513	Roadway	Crack	3	Yes Bad
659	26.288970	-81.783339	Roadway	Void	3	No
660	26.288970	-81.783339	Roadway	Crack	3	No
661	26.289154	-81.783264	Roadway	Void	3	No
669	26.289784	-81.783070	Roadway	Void	3	No
671	26.289872	-81.783052	Roadway	Ridge	3	No
673	26.289896	-81.783038	Roadway	Void	3	No
674	26.289920	-81.783047	Roadway	Void	3	No
675	26.289920	-81.783047	Roadway	Crack	3	No
677	26.288211	-81.784234	Patio	Ridge	3	No
684	26.288093	-81.783778	Guest Parking	Void	3	No
685	26.288093	-81.783778	Guest Parking	Crack	3	No
686	26.288109	-81.783797	Guest Parking	Crack	3	No
687	26.288117	-81.783825	Guest Parking	Crack	3	No
688	26.288120	-81.783851	Guest Parking	Crack	3	No
696	26.288173	-81.784213	Car Port	Void	3	No
698	26.288183	-81.784323	Car Port	Ridge	3	No
701	26.288180	-81.784345	Guest Parking	Void	3	No
702	26.288367	-81.783588	Sidewalk	Ridge	3	No
703	26.288399	-81.783563	Sidewalk	Ridge	3	No
706	26.288623	-81.783545	Sidewalk	Ridge	3	No
728	26.289205	-81.783464	Sidewalk	Ridge	3	No
733	26.288815	-81.783429	Guest Parking	Crack	3	No
747	26.289307	-81.783232	Guest Parking	Ridge	3	No
749	26.289343	-81.783184	Guest Parking	Void	3	No
750	26.289343	-81.783184	Guest Parking	Void	3	No
751	26.289351	-81.783177	Guest Parking	Ridge	3	No
756	26.289434	-81.783138	Car Port	Ridge	3	No
760	26.289589	-81.783125	Car Port	Ridge	3	No
761	26.289617	-81.783122	Car Port	Ridge	3	No
762	26.289648	-81.783120	Car Port	Ridge	3	No
764	26.289687	-81.783113	Guest Parking	Void	3	No
765	26.289701	-81.783111	Guest Parking	Ridge	3	No
767	26.289732	-81.783132	Guest Parking	Ridge	3	No
769	26.289725	-81.783133	Guest Parking	Void	3	No
774	26.289764	-81.783123	Guest Parking	Void	3	No
775	26.289775	-81.783122	Guest Parking	Crack	3	No
777	26.289786	-81.783101	Guest Parking	Ridge	3	No
778	26.289820	-81.783097	Guest Parking	Ridge	3	No
780	26.289873	-81.783089	Guest Parking	Ridge	3	No
781	26.289873	-81.783089	Guest Parking	Void	3	No
784	26.289896	-81.783065	Guest Parking	Void	3	No
785	26.289921	-81.783087	Guest Parking	Ridge	3	No
787	26.289948	-81.783089	Guest Parking	Ridge	3	No
788	26.289956	-81.783065	Guest Parking	Void	3	No
800	26.289098	-81.783261	Roadway	Iron Oxide	3	No
5	26.291763	-81.783144	Driveway	Crack	4	Yes Good
7	26.291848	-81.783039	Driveway	Crack	4	Yes Bad
9	26.291860	-81.783014	Driveway	Crack	4	No
10	26.291860	-81.783014	Driveway	Crack	4	No
14	26.291842	-81.782480	Driveway	Void	4	No

17	26.292428	-81.782723	Sidewalk	Crack	4	No
18	26.292378	-81.782761	Driveway	Crack	4	No
20	26.292190	-81.782912	Driveway	Crack	4	No
22	26.292152	-81.782869	Driveway	Crack	4	No
23	26.292190	-81.782740	Driveway	Crack	4	No
24	26.292113	-81.782826	Driveway	Crack	4	No
25	26.292113	-81.782783	Driveway	Crack	4	No
26	26.292152	-81.782826	Driveway	Crack	4	No
28	26.291966	-81.782570	Driveway	Crack	4	No
29	26.291984	-81.782548	Driveway	Crack	4	No
32	26.291984	-81.782548	Driveway	Crack	4	No
34	26.291862	-81.782869	Sidewalk	Crack	4	No
35	26.291824	-81.782869	Driveway	Crack	4	No
40	26.291901	-81.782654	Driveway	Crack	4	No
44	26.291901	-81.782697	Driveway	Crack	4	No
45	26.291785	-81.782692	Driveway	Crack	4	No
46	26.291735	-81.782710	Driveway	Crack	4	No
47	26.291764	-81.782673	Driveway	Crack	4	No
48	26.291786	-81.782760	Driveway	Crack	4	No
49	26.291785	-81.782673	Driveway	Crack	4	No
50	26.291775	-81.782673	Driveway	Crack	4	No
51	26.291776	-81.782673	Driveway	Cosmetic	4	No
54	26.291876	-81.782602	Roadway	Crack	4	No
57	26.291750	-81.782738	Guest Parking	Crack	4	No
59	26.291683	-81.782762	Roadway	Crack	4	No
60	26.291674	-81.782798	Roadway	Void	4	No
61	26.291674	-81.782798	Roadway	Crack	4	No
63	26.291694	-81.782721	Driveway	Crack	4	No
64	26.291730	-81.782687	Sidewalk	Crack	4	No
65	26.291648	-81.782682	Driveway	Crack	4	No
69	26.291561	-81.782725	Driveway	Crack	4	No
72	26.291614	-81.782805	Roadway	Crack	4	No
73	26.291614	-81.782805	Driveway	Crack	4	No
74	26.291552	-81.782794	Roadway	Crack	4	No
77	26.291494	-81.782714	Driveway	Crack	4	No
78	26.291475	-81.782693	Driveway	Void	4	No
79	26.291475	-81.782693	Driveway	Crack	4	No
83	26.291527	-81.782709	Driveway	Crack	4	No
84	26.291531	-81.782780	Roadway	Crack	4	No
85	26.291524	-81.782755	Roadway	Crack	4	No
86	26.291475	-81.782744	Roadway	Crack	4	No
88	26.291494	-81.782702	Driveway	Crack	4	No
97	26.291314	-81.782778	Roadway	Crack	4	No
99	26.291365	-81.782760	Roadway	Crack	4	No
102	26.291349	-81.782698	Driveway	Crack	4	No
106	26.291348	-81.782770	Roadway	Crack	4	No
117	26.291211	-81.782744	Roadway	Void	4	No
123	26.291139	-81.782739	Driveway	Crack	4	No
128	26.291101	-81.782765	Driveway	Crack	4	No
129	26.291082	-81.782676	Driveway	Crack	4	No
130	26.291108	-81.782811	Roadway	Crack	4	No
136	26.291034	-81.782738	Driveway	Crack	4	No

138	26.291134	-81.782758	Driveway	Crack	4	No
139	26.291008	-81.782747	Driveway	Crack	4	No
142	26.291014	-81.782767	Driveway	Crack	4	No
143	26.291014	-81.782813	Roadway	Crack	4	No
148	26.290912	-81.782742	Driveway	Crack	4	No
155	26.290836	-81.782831	Roadway	Void	4	No
156	26.290819	-81.782832	Roadway	Void	4	No
158	26.290810	-81.782814	Driveway	Crack	4	No
159	26.290805	-81.782766	Driveway	Crack	4	No
160	26.290794	-81.782771	Driveway	Crack	4	No
164	26.290718	-81.782816	Roadway	Void	4	No
173	26.291799	-81.782822	Roadway	Void	4	No
174	26.290607	-81.782941	Roadway	Crack	4	No
177	26.290489	-81.783115	Roadway	Crack	4	No
181	26.290431	-81.783207	Roadway	Crack	4	No
186	26.290337	-81.783512	Roadway	Void	4	No
189	26.290243	-81.783488	Roadway	Void	4	No
193	26.290336	-81.783257	Roadway	Void	4	No
195	26.290394	-81.783101	Driveway	Crack	4	No
196	26.290473	-81.783019	Driveway	Crack	4	No
198	26.290482	-81.782918	Driveway	Crack	4	No
200	26.290478	-81.782943	Driveway	Crack	4	No
201	26.290461	-81.782938	Driveway	Crack	4	No
202	26.290458	-81.782986	Driveway	Void	4	No
203	26.290402	-81.783032	Driveway	Crack	4	No
205	26.290388	-81.782881	Driveway	Crack	4	No
208	26.290370	-81.782952	Driveway	Crack	4	No
209	26.290353	-81.782992	Driveway	Crack	4	No
212	26.290344	-81.783006	Driveway	Void	4	No
215	26.290360	-81.782862	Driveway	Crack	4	No
218	26.290301	-81.783056	Driveway	Void	4	No
219	26.290301	-81.783056	Driveway	Crack	4	No
220	26.290263	-81.782937	Driveway	Void	4	No
222	26.290255	-81.783029	Driveway	Crack	4	No
223	26.290255	-81.783029	Driveway	Crack	4	No
224	26.290211	-81.783084	Driveway	Crack	4	No
226	26.290237	-81.782881	Driveway	Crack	4	No
227	26.290176	-81.782875	Driveway	Void	4	No
228	26.290171	-81.782930	Driveway	Crack	4	No
230	26.290262	-81.783007	Driveway	Void	4	No
231	26.290172	-81.783007	Driveway	Void	4	No
233	26.290230	-81.783101	Driveway	Void	4	No
235	26.290144	-81.783008	Driveway	Void	4	No
238	26.290051	-81.782958	Driveway	Void	4	No
239	26.290051	-81.782990	Driveway	Crack	4	No
244	26.290023	-81.782962	Driveway	Crack	4	No
246	26.290023	-81.782962	Driveway	Void	4	No
247	26.289964	-81.782961	Gutter	Void	4	No
250	26.289935	-81.782911	Driveway	Crack	4	No
251	26.289924	-81.783006	Driveway	Void	4	No
257	26.289752	-81.782871	Roadway	Void	4	No
258	26.289763	-81.782931	Roadway	Crack	4	No

260	26.289758	-81.783033	Driveway	Void	4	No
263	26.289695	-81.782901	Gutter	Void	4	No
264	26.289700	-81.782934	Sidewalk	Crack	4	No
267	26.289709	-81.783011	Driveway	Void	4	No
275	26.289573	-81.782931	Driveway	Crack	4	No
283	26.289497	-81.783051	Driveway	Void	4	No
286	26.289479	-81.783075	Driveway	Ridge	4	No
287	26.289489	-81.783053	Roadway	Void	4	No
293	26.288735	-81.783360	Driveway	Crack	4	No
296	26.288587	-81.783390	Roadway	Crack	4	No
300	26.288309	-81.783447	Driveway	Void	4	No
303	26.288910	-81.783285	Driveway	Void	4	No
304	26.288892	-81.783298	Driveway	Crack	4	No
308	26.288731	-81.783354	Driveway	Void	4	No
311	26.288612	-81.783381	Driveway	Void	4	No
313	26.288419	-81.783404	Driveway	Crack	4	No
314	26.288402	-81.783404	Driveway	Crack	4	No
318	26.288348	-81.783403	Driveway	Crack	4	No
320	26.288307	-81.783396	Sidewalk	Crack	4	No
323	26.288228	-81.783413	Driveway	Void	4	No
345	26.288059	-81.783656	Driveway	Crack	4	No
349	26.288046	-81.783710	Driveway	Crack	4	No
353	26.288044	-81.783790	Driveway	Crack	4	No
355	26.288025	-81.783889	Driveway	Void	4	No
358	26.288042	-81.783999	Driveway	Void	4	No
359	26.292144	-81.782709	Driveway	Crack	4	No
362	26.288016	-81.783974	Driveway	Crack	4	No
364	26.287983	-81.783980	Driveway	Crack	4	No
368	26.288036	-81.784170	Driveway	Crack	4	No
369	26.288062	-81.784260	Driveway	Crack	4	No
370	26.288053	-81.784227	Driveway	Crack	4	No
377	26.288282	-81.785181	Driveway	Crack	4	No
379	26.288286	-81.785206	Driveway	Void	4	No
380	26.288281	-81.785266	Driveway	Crack	4	No
381	26.288287	-81.785243	Sidewalk	Crack	4	No
382	26.288309	-81.785308	Driveway	Crack	4	No
385	26.288359	-81.785375	Roadway	Void	4	No
386	26.288318	-81.785387	Driveway	Void	4	No
387	26.288329	-81.785426	Driveway	Void	4	No
389	26.288334	-81.785529	Driveway	Void	4	No
391	26.288447	-81.785401	Roadway	Crack	4	No
393	26.288465	-81.785389	Roadway	Void	4	No
394	26.288515	-81.785396	Driveway	Crack	4	No
395	26.288455	-81.785452	Sidewalk	Crack	4	No
402	26.288723	-81.785361	Driveway	Crack	4	No
403	26.288740	-81.785365	Driveway	Void	4	No
404	26.288856	-81.785344	Driveway	Void	4	No
409	26.289308	-81.785254	Driveway	Void	4	No
410	26.289460	-81.784948	Roadway	Crack	4	No
432	26.289838	-81.784612	Roadway	Crack	4	No
438	26.289872	-81.784595	Driveway	Void	4	No
439	26.290006	-81.784529	Sidewalk	Void	4	No

442	26.289970	-81.784544	Driveway	Void	4	No
443	26.289998	-81.784522	Driveway	Crack	4	No
444	26.290037	-81.784413	Roadway	Void	4	No
446	26.290139	-81.784369	Driveway	Void	4	No
449	26.290167	-81.783768	Roadway	Crack	4	No
456	26.290198	-81.784333	Roadway	Void	4	No
457	26.290182	-81.784313	Roadway	Void	4	No
463	26.290229	-81.783688	Roadway	Void	4	No
464	26.290241	-81.783697	Roadway	Void	4	No
465	26.290270	-81.783645	Roadway	Void	4	No
472	26.289961	-81.783745	Sidewalk	Ridge	4	No
473	26.289945	-81.783733	Sidewalk	Ridge	4	No
475	26.289941	-81.783824	Sidewalk	Ridge	4	No
478	26.289954	-81.783947	Handicapped Parking	Crack	4	No
480	26.289989	-81.783921	Car Port	Void	4	No
481	26.290009	-81.783855	Car Port	Crack	4	No
483	26.290029	-81.783773	Car Port	Void	4	No
484	26.290047	-81.783611	Car Port	Crack	4	No
485	26.290025	-81.783598	Car Port	Void	4	No
488	26.290040	-81.783568	Guest Parking	Void	4	No
491	26.290071	-81.783490	Guest Parking	Void	4	No
493	26.290066	-81.783466	Guest Parking	Void	4	No
496	26.290146	-81.783628	Guest Parking	Ridge	4	No
505	26.290147	-81.783777	O Lot	Void	4	No
522	26.290074	-81.783796	O Lot	Void	4	No
523	26.290068	-81.783806	O Lot	Crack	4	No
525	26.290074	-81.783786	O Lot	Crack	4	No
526	26.290044	-81.783744	O Lot	Void	4	No
527	26.290048	-81.783723	O Lot	Crack	4	No
529	26.290087	-81.783760	O Lot	Ridge	4	No
551	26.290106	-81.783582	O Lot	Crack	4	No
552	26.290106	-81.783582	O Lot	Crack	4	No
553	26.290086	-81.783515	O Lot	Ridge	4	No
554	26.290083	-81.783532	O Lot	Crack	4	No
558	26.289990	-81.784427	Roadway	Void	4	No
559	26.290025	-81.784344	Roadway	Crack	4	No
560	26.290007	-81.784372	Roadway	Crack	4	No
561	26.290001	-81.784360	Roadway	Crack	4	No
562	26.289987	-81.784393	Roadway	Crack	4	No
565	26.289919	-81.784423	Roadway	Crack	4	No
566	26.289898	-81.784448	Roadway	Crack	4	No
567	26.289896	-81.784438	Roadway	Crack	4	No
570	26.289597	-81.784726	Patio	Crack	4	No
571	26.289597	-81.784726	Sidewalk	Crack	4	No
572	26.289452	-81.784750	Sidewalk	Void	4	No
575	26.289873	-81.784512	Roadway	Crack	4	No
580	26.289826	-81.784557	Roadway	Crack	4	No
591	26.289611	-81.784731	Roadway	Crack	4	No
595	26.289611	-81.784728	Car Port	Crack	4	No
597	26.289659	-81.784685	Car Port	Crack	4	No
598	26.289680	-81.784683	Car Port	Crack	4	No
600	26.289682	-81.784640	Guest Parking	Crack	4	No

601	26.289693	-81.784624	Guest Parking	Crack	4	No
603	26.289728	-81.784602	Guest Parking	Crack	4	No
606	26.289764	-81.784576	Car Port	Void	4	No
607	26.289760	-81.784564	Car Port	Crack	4	No
608	26.289785	-81.784553	Car Port	Crack	4	No
609	26.289827	-81.784518	Car Port	Crack	4	No
610	26.289850	-81.784498	Car Port	Crack	4	No
612	26.289861	-81.784477	Guest Parking	Crack	4	No
616	26.288909	-81.785279	Roadway	Crack	4	No
618	26.289194	-81.785084	Sidewalk	Ridge	4	No
620	26.289068	-81.785310	Driveway	Crack	4	
621	26.289058	-81.785420	Driveway	Crack	4	
624	26.289410	-81.784864	Guest Parking	Void	4	No
625	26.289408	-81.784896	Car Port	Crack	4	No
626	26.289384	-81.784923	Car Port	Crack	4	No
627	26.289376	-81.784940	Car Port	Crack	4	No
632	26.289176	-81.785216	Car Port	Void	4	No
633	26.289160	-81.785221	Car Port	Void	4	No
634	26.289149	-81.785181	Car Port	Crack	4	No
637	26.289064	-81.785210	Car Port	Ridge	4	No
638	26.289006	-81.785222	Guest Parking	Void	4	No
639	26.289006	-81.785222	Guest Parking	Ridge	4	No
640	26.288989	-81.785224	Guest Parking	Void	4	No
641	26.288989	-81.785224	Guest Parking	Crack	4	No
643	26.288975	-81.785230	Guest Parking	Crack	4	No
645	26.288933	-81.785234	Guest Parking	Void	4	No
648	26.288519	-81.785275	Guest Parking	Void	4	No
652	26.288080	-81.783832	Roadway	Crack	4	No
656	26.288136	-81.783579	Roadway	Crack	4	No
662	26.289154	-81.783264	Roadway	Crack	4	No
664	26.289557	-81.783082	Roadway	Crack	4	No
666	26.289764	-81.783064	Roadway	Void	4	No
672	26.289890	-81.783056	Roadway	Void	4	No
678	26.288217	-81.784248	Patio	Crack	4	No
679	26.288199	-81.784214	Sidewalk	Crack	4	No
680	26.288163	-81.784108	Patio	Ridge	4	No
681	26.288163	-81.784108	Patio	Crack	4	No
683	26.288163	-81.784108	Sidewalk	Ridge	4	No
689	26.288127	-81.783927	Car Port	Void	4	No
690	26.288134	-81.783951	Car Port	Crack	4	No
692	26.288160	-81.784059	Guest Parking	Ridge	4	No
695	26.288160	-81.784139	Guest Parking	Crack	4	No
697	26.288176	-81.784250	Car Port	Crack	4	No
699	26.288180	-81.784345	Guest Parking	Crack	4	No
704	26.288604	-81.783569	Patio	Crack	4	No
707	26.288788	-81.783551	Sidewalk	Ridge	4	No
708	26.288775	-81.783463	Guest Parking	Crack	4	No
709	26.288645	-81.783541	Guest Parking	Void	4	No
710	26.288645	-81.783541	Guest Parking	Crack	4	No
711	26.288607	-81.783531	Guest Parking	Crack	4	No
717	26.288451	-81.783502	Car Port	Ridge	4	No
718	26.288439	-81.783521	Guest Parking	Void	4	No

719	26.288391	-81.783526	Guest Parking	Crack	4	No
720	26.288366	-81.783525	Guest Parking	Crack	4	No
721	26.288345	-81.783513	Guest Parking	Void	4	No
722	26.288336	-81.783532	Guest Parking	Void	4	No
725	26.288870	-81.783466	Sidewalk	Void	4	No
729	26.289615	-81.783225	Sidewalk	Ridge	4	No
730	26.289705	-81.783225	Sidewalk	Ridge	4	No
731	26.289695	-81.783195	Sidewalk	Ridge	4	No
735	26.288835	-81.783445	Guest Parking	Ridge	4	No
736	26.288895	-81.783415	Car Port	Crack	4	No
737	26.288915	-81.783405	Car Port	Crack	4	No
738	26.288995	-81.783405	Guest Parking	Ridge	4	No
739	26.289020	-81.783375	Guest Parking	Crack	4	No
740	26.289135	-81.783335	Car Port	Ridge	4	No
741	26.289135	-81.783345	Car Port	Void	4	No
742	26.289165	-81.783335	Guest Parking	Void	4	No
743	26.289240	-81.783299	Guest Parking	Void	4	No
744	26.289240	-81.783299	Guest Parking	Ridge	4	No
748	26.289327	-81.783201	Guest Parking	Void	4	No
753	26.289369	-81.783165	Guest Parking	Void	4	No
754	26.289411	-81.783124	Guest Parking	Ridge	4	No
755	26.289401	-81.783152	Guest Parking	Void	4	No
757	26.289451	-81.783142	Car Port	Ridge	4	No
758	26.289480	-81.783140	Car Port	Crack	4	No
759	26.289589	-81.783125	Car Port	Crack	4	No
763	26.289669	-81.783112	Car Port	Ridge	4	No
766	26.289702	-81.783127	Guest Parking	Ridge	4	No
771	26.289740	-81.783135	Guest Parking	Ridge	4	No
773	26.289739	-81.783112	Guest Parking	Void	4	No
ridges				123	137	ci
cracks				275		

Closest Condo	Building	Length	Width	Depth or Height	Voids	Cracks	Slabs	Pic	Optional Notes
C-2	C	8	4	0.5	0	0	0	Yes	
C-3	C	9	3	1	1	0	0	Yes	
C-3	C	7	3	0.5	1	0	0	Yes	
C-4	C	24	3	0.5	1	0	0	Yes	
C-6	C	9	3	1.5	1	0	0	Yes	
C-6	C	9	6	1	1	0	0	Yes	
C-7	C	6	3	0.5	4	0	0	Yes	
C-9	C	3	1	0.5	3	0	0	Yes	
C-10	C	8	4	0.75	7	0	0	Yes	
C-10	C	12	4	0.5	1	0	0	Yes	
C-10	C	4	3	0.5	1	0	0	Yes	
D-1	D	8	6	1.5	2	0	0	Yes	
D-1	D	36	6	0.5	0	1	0	Yes	
D-1	D	7	5	1	2	0	0	Yes	
D-2	D	6	4	2	1	0	0	Yes	
D-3	D	7	4	0.5	2	0	0	Yes	
D-3	D	5	3	1	1	0	0	Yes	
D-4	D	5	4	1	4	0	0	Yes	
D-4	D	12	8	1.5	1	0	0	Yes	
D-5	D	6	6	1	1	0	0	Yes	
D-8	D	7	3	1	1	0	0	Yes	
D-8	D	6	4	1	1	0	0	Yes	
D-10	D	12	0.5	0.25	0	0	0	Yes	
E-1	E	3	3	0.25	15	0	0	Yes	
O-1	O	9	3	1	1	0	0	Yes	
O-1	O	84	18	0.5	9	0	0	Yes	Need to replace
O-1	O	72	0.25	0.3	0	0	0	Yes	
O-1	O	4	4	0.5	1	0	0	Yes	
O-1	O	6	3	1	3	0	0	Yes	
E-1	E	192	30	0.25	0	0	0	Yes	Replace and rer
E-1	E	96	0.125	0.25	0	1	0	Yes	
E-1	E	6	4	0.5	5	0	0	Yes	
E-4	E	5	5	1	1	0	0	Yes	
E-4	E	3	3	0.5	6	0	0	Yes	
F-1	F	6	2	0.5	1	0	0	Yes	
F-2	F	4	2	0.25	16	0	0	Yes	
F-4	F	12	3	0.5	1	0	0	Yes	
F-4	F	6	3	1	1	0	0	Yes	
F-4	F	5	2	1	2	0	0	Yes	
F-6	F	7	7	1	1	0	0	Yes	
F-7	F	4	3	1	1	0	0	Yes	
F-11	F	120	0.25	0.5	0	0	0	Yes	
G-5	G	10	3	1	1	0	0	Yes	
G-9	G	8	2	1.25	2	0	0	Yes	
H-2	H	9	4	0.50	1	0	0	Yes	
H-7	H	18	0.25	0.25	0	0	0	Yes	
H-9	H	8	2.5	0.3	0	0	0	Yes	
H-12	H	18	22	0.25	0	0	0	Yes	
I-2	I	7	7	0.3	1	0	0	Yes	
I-3	I	4	1.5	0.5	4	0	0	Yes	

I-7	I	9	6	1.5	1	0	0	Yes	
I-7	I	16	6	1	1	0	0	Yes	
I-7	I	11	6	1.5	1	0	0	Yes	
I-9	I	12	5	0.5	1	0	0	Yes	
I-10	I	12	4	1	1	0	0	Yes	
I-11	I	5	3	0.5	3	0	0	Yes	
I-12	I	5	5	0.5	1	0	0	Yes	
I-12	I	6	3	0.25	1	0	0	Yes	
I-12	I	12	4	0.25	1	0	0	Yes	
I-12	I	5	3	0.25	5	0	0	Yes	one is large, on
K-4	K	8	3	1	1	0	0	Yes	
K-12	K	5	2	0.25	1	0	0	Yes	
L-4	L	12	4	1	1	0	0	Yes	
M-1	M	4	4	0.25	1	0	0	Yes	
M-1	M	4	2	0.25	1	0	0	Yes	
M-1	M	8	0.3	0.25	0	1	0	Yes	
M-1	M	12	5	1	1	0	0	Yes	
M-1	M	24	0.25	0.25	0	0	0	Yes	
M-1	M	192	0.25	0.25	0	1	0	Yes	
M-1	M	12	5	2	1	0	0	Yes	
M-3	M	24	5	0.5	1	0	0	Yes	
M-4	M	4	3	1	1	0	0	Yes	
M-5	M	7	2	0.25	1	0	0	Yes	
M-5	M	3	3	0.25	1	0	0	Yes	
M-5	M	7	3	0.25	1	0	0	Yes	
M-10	M	40	0.3	0.25	0	1	0	Yes	
O-7	O	48	24	0.25	1	0	0	Yes	
O-8	O	48	0.25	0.25	0	0	0	Yes	
O-10	O	144	12	0.5	0	0	0	Yes	
Club House	Club House	6	3	0.25	1	0	0	Yes	
Club House	Club House	5	4	1	1	0	0	Yes	
O-1	O	36	0.25	0.35	0	0	0	Yes	
O-3	O	204	0.25	0.25	0	0	0	Yes	Right in plain sig
O-9	O	36	0.25	0.5	0	0	0	Yes	
O-10	O	36	0.25	0.25	0	0	0	Yes	
O-4	O	7	4	0.5	1	0	0	Yes	
O-3	O	3	1	0.25	5	0	0	Yes	
O-5	O	12	2	1	1	0	0	Yes	entry
O-6	O	10	4	1	1	0	0	Yes	entry
O-6	O	10	4	1	1	0	0	Yes	entry
O-7	O	4	2	0.5	4	0	0	Yes	entry
O-10	O	3	1	0.3	7	0	0	Yes	slab 2
O-6	O	18	3	0.5	1	0	0	Yes	slab 7
O-5	O	6	2	0.5	6	0	0	Yes	slab 10
O-5	O	36	0.25	0.5	0	0	0	Yes	slab 10
O-4	O	12	6	1	1	0	0	Yes	slab 11
O-4	O	48	0.25	0.5	0	0	0	Yes	slab 12
O-2	O	6	3	0.5	1	0	0	Yes	slab 14
O-2	O	9	5	0.5	2	0	0	Yes	slab 14
O-1	O	3	2	0.5	18	0	0	Yes	slab 15 needs re
O-1	O	96	0.25	0.33	0	0	0	Yes	slab 15 needs re
O-1	O	360	0.25	0.25	0	1	0	Yes	slab 15 needs re

O-1	O	4	2	1	8	0	0	Yes	slab 16 needs re
O-1	O	48	0.25	0.25	0	0	0	Yes	slab 16 needs re
Club House	Club House	288	0.25	0.25	0	0	0	Yes	
N-1	N	10	2	0.5	2	0	0	Yes	
N-7	N	24	0.25	1	0	0	0	Yes	
T-1	T	8	2	0.5	1	0	0	Yes	
P-10	P	7	3	0.25	2	0	0	Yes	
P-10	P	6	3	1	2	0	0	Yes	
S-6	S	5	2	0.5	1	0	0	Yes	
S-1	S	4	4	0.25	1	0	0	Yes	
R-6	R	108	0.25	0.25	0	0	0	Yes	
R-6	R	108	0.25	0.25	0	0	0	Yes	
R-3	R	112	0.25	0.25	0	0	0	Yes	bottom of posts
R-3	R	112	0.25	0.25	0	0	0	Yes	bottom of posts
R-2	R	112	0.25	0.25	0	0	0	Yes	bottom of posts
R-1	R	20	4	0.25	1	0	0	Yes	
Q-4	Q	36	0.25	0.25	0	0	0	Yes	
Q-1	Q	12	0.25	1	0	0	0	Yes	
P-1	P	24	18	0.25	1	0	0	Yes	
P-2	P	12	1	1	0	0	0	Yes	
P-10	P	96	0.25	0.25	0	0	0	Yes	
P-10	P	12	3	0.25	1	0	0	Yes	
P-10	P	84	0.25	0.5	0	0	0	Yes	
P-10	P	120	0.25	0.25	0	0	0	Yes	
P-10	P	7	7	.5	1	0	0	Yes	
P-10	P	12	4	1.5	1	0	0	Yes	
B-12	B				0	0	.5	Yes	Between B and
F-4	F				0	0	8	Yes	F-4 thru F-6 sing
F-7	F				0	0	1	Yes	single lane near
F-9	F				0	0	9	Yes	F-9 thru F-12 sir
I-3	I				0	0	10	Yes	I-3 thru I-8 single
I-11	I				0	0	20	Yes	I-11 thru round c
E-9	E				0	0	0	Yes	E-9 and E-10 ha
E-11	E				0	0	0	Yes	E-11 and E-12 h
S-9	S				0	12	0	Yes	Cracked and old
A-1	A	60	0.5	0.25	0	1	0	Yes	
A-2	A	3	1	0.5	1	0	0	Yes	
A-10	A	60	0.25	0.75	0	0	0	Yes	
B-7	B	3	2	1	2	0	0	Yes	
B-10	B	3	2	0.5	7	0	0	Yes	
B-12	B	3	1	0.5	5	0	0	Yes	
A-10	A	3	1	0.5	1	0	0	Yes	
C-2	C	5	4	0.25	1	0	0	Yes	
C-2	C	4	1	0.25	9	0	0	Yes	
C-4	C	5	1	0.25	12	0	0	Yes	
C-6	C	3	2	0.25	2	0	0	Yes	
C-6	C	120	0.25	0.25	0	1	0	Yes	
C-6	C	4	3	0.5	2	0	0	Yes	
C-6	C	192	0.25	0.25	0	1	0	Yes	
C-7	C	5	2	0.25	3	0	0	Yes	
C-7	C	4	2	0.25	3	0	0	Yes	
C-8	C	216	0.25	0.25	0	1	0	Yes	

C-8	C	8	2	0.25	6	0	0	Yes
C-9	C	7	1	0.5	1	0	0	Yes
C-10	C	66	0.25	0.25	0	1	0	Yes
D-2	D	5	2	0.25	2	0	0	Yes
D-5	D	8	2	0.125	1	0	0	Yes
D-6	D	3	3	0.25	2	0	0	Yes
D-7	D	5	1	0.5	1	0	0	Yes
D-10	D	2	1	0.25	10	0	0	Yes
E-1	E	5	4	0.5	1	0	0	Yes
E-3	E	3	1	0.25	7	0	0	Yes
E-10	E	48	0.25	0.25	0	0	0	Yes
E-10	E	3	2	0.25	6	0	0	Yes
E-10	E	72	0.25	0.25	0	0	0	Yes
E-10	E	108	0.25	0.25	0	1	0	Yes
E-10	E	4	3	1	7	0	0	Yes
E-11	E	3	1	1	6	0	0	Yes
F-2	F	4	2	0.25	2	0	0	Yes
F-2	F	144	0.25	0.25	0	0	0	Yes
F-3	F	6	5	0.25	1	0	0	Yes
F-3	F	4	1	0.25	3	0	0	Yes
F-3	F	3	1	0.25	5	0	0	Yes
F-4	F	3	1	0.25	5	0	0	Yes
F-5	F	4	2	0.25	4	0	0	Yes
F-6	F	132	0.5	0.25	0	1	0	Yes
F-7	F	5	2	0.5	1	0	0	Yes
F-9	F	5	3	1	1	0	0	Yes
F-9	F	5	4	1	1	0	0	Yes
F-11	F	240	0.25	0.25	0	1	0	Yes
F-12	F	3	3	0.25	5	0	0	Yes
G-6	G	120	0.25	0.25	0	0	0	Yes
G-10	G	3	2	0.5	2	0	0	Yes
G-10	G	3	2	0.5	2	0	0	Yes
H-4	H	4	2	0.5	0	0	0	Yes
H-5	H	36	0.25	0.25	0	1	0	Yes
H-5	H	4	1	0.3	2	0	0	Yes
H-7	H	6	2	0.5	3	0	0	Yes
H-7	H	5	2	0.3	1	0	0	Yes
H-8	H	3	1	0.3	3	0	0	Yes
H-8	H	3	1	0.3	2	0	0	Yes
H-10	H	372	0.3	0.25	0	1	0	Yes
H-9	H	36	0.3	0.25	0	1	0	Yes
H-11	H	40	2	0.3	0	0	0	Yes
H-11	H	10	2.5	,5	2	0	0	Yes
H-11	H	252	0.25	0.24	0	1	0	Yes
H-12	H	4	1	0.5	8	0	0	Yes
H-12	H	1	1	0.25	8	0	0	Yes
I-2	I	6	3	1	0	0	0	Yes
B-6	B	3	3	0.25	2	0	0	Yes
I-11	I	12	0.25	0.25	0	1	0	Yes
J-10	J	2	1	0.25	0	0	0	Yes
K-1	K	48	0.25	0.25	0	0	0	Yes
K-2	K	14	13	0.25	1	0	0	Yes

One void is 6x6

K-3	K	5	2	0.5	2	0	0	Yes	
K-3	K	8	2	0.25	1	0	0	Yes	
M-3	M	24	48	0.25	0	0	0	Yes	should be replac
M-6	M	192	0.25	0.25	0	1	0	Yes	
O-6	O	6	1	0.25	3	0	0	Yes	
O-10	O	7	5	0.5	0	0	0	Yes	
Club House	Club House	24	2	0.25	1	0	0	Yes	
O-1	O	120	0.25	0.25	0	0	0	Yes	
O-1	O	36	0.25	0.25	0	0	0	Yes	
O-1	O	4	1	0.35	2	0	0	Yes	
O-1	O	36	0.25	0.25	0	0	0	Yes	
O-1	O	36	0.25	0.3	0	0	0	Yes	
O-1	O	72	0.25	0.25	0	0	0	Yes	
O-4	O	3	2	0.6	2	0	0	Yes	
O-10	O	444	0.25	0.25	0	1	0	Yes	slab 2
O-9	O	6	3	0.25	4	0	0	Yes	slab 4
O-4	O	4	2	0.25	5	0	0	Yes	slab 11
O-4	O	144	0.25	0.25	0	1	0	Yes	slab 11
O-4	O	3	1	0.25	5	0	0	Yes	slab 12
O-3	O	3	2	0.25	4	0	0	Yes	slab 13
O-2	O	48	0.25	0.25	0	0	0	Yes	slab 14
O-2	O	228	0.25	0.25	0	1	0	Yes	slab 14
N-3	N	5	3	0.25	9	0	0	Yes	
N-3	N	18	3	0.5	1	0	0	Yes	
N-3	N	4	2	0.5	3	0	0	Yes	
N-4	N	3	2	0.5	6	0	0	Yes	
N-5	N	7	0.25	0.5	1	0	0	Yes	
N-6	N	16	3	0.5	1	0	0	Yes	
N-7	N	16	3	1	1	0	0	Yes	
N-7	N	4	2	0.5	4	0	0	Yes	
N-5	N	4	4	0.5	1	0	0	Yes	
U-10	U	12	0.25	0.25	0	0	0	Yes	
U-6	U	4	2	0.25	6	0	0	Yes	
U-10	U	36	0.25	0.25	0	0	0	Yes	
T-1	T	6	6	1	1	0	0	Yes	
T-6	T	60	0.25	0.5	0	0	0	Yes	
S-10	S	6	2	0.5	1	0	0	Yes	
R-1	R	4	2	.5	3	0	0	Yes	
R-1	R	144	0.5	0.25	0	1	0	Yes	
P-7	P	5	2	0.7	15	0	0	Yes	
P-10	P	5	1	0.7	3	0	0	Yes	
P-10	P	144	0.25	0.25	0	1	0	Yes	
S-1	S	36	0.25	0.6	0	0	0	Yes	
S-6	S	48	0.25	0.5	0	0	0	Yes	
S-8	S	120	0.25	0.25	0	0	0	Yes	
S-6	S	24	2	0.25	1	0	0	Yes	
R-6	R	36	0.25	0.25	0	0	0	Yes	
R-1	R	10	3	0.25	1	0	0	Yes	
Q-4	Q	36	0.25	0.25	0	0	0	Yes	
Q-1	Q	14	2	0.25	1	0	0	Yes	
Q-10	Q	72	0.25	0.25	0	0	0	Yes	
P-10	P	72	0.25	0.25	0	0	0	Yes	

P-10	P	120	0.25	0.25	0	0	0	Yes	
B-3	B				0	0	14	Yes	B-3 thru B-6, bo
A-9	A				0	0	9	Yes	A-9 thru A-10, b
A-6	A				0	0	4	Yes	A-6 thru A-7 sing
A-2	A				0	0	16	Yes	A-2 thru A-5 bot
A-1	A				0	0	3	Yes	A-1 thru curve s
E-4	E				0	0	15	Yes	E-4 thru E-12 si
F-1	F				0	0	2	Yes	F-1 thru F-2 sing
R-5	R				0	0	10	Yes	R-5 thru R-10 si
H-1	H				0	0	8	Yes	H-1 thru H5 sing
A-1	A	1	2	0.25	2	0	0	Yes	
A-2	A	2	1.5	0.25	2	0	0	Yes	
A-4	A	120	0.25	0.25	0	1	0	Yes	
A-6	A	36	0.25	0.25	0	1	0	Yes	
A-8	A	204	0.25	0.25	0	1	0	Yes	
A-9	A	120	0.25	0.25	0	1	0	Yes	
A-9	A	120	2	0.5	0	1	0	Yes	
A-1	A	35	0.25	0.125	0	0	0	Yes	
B-2	B	3	2	1	1	0	0	Yes	
B-2	B	1	1	1	0	0	0	Yes	
B-5	B	360	0.25	0.25	0	1	0	Yes	
B-8	B	3	1	0.25	4	0	0	Yes	
B-8	B	36	0.25	0.25	0	0	0	Yes	
B-9	B	84	0.25	0.25	0	1	0	Yes	
B-9	B	5	3	0.25	1	0	0	Yes	
B-9	B	48	0.25	0.25	0	1	0	Yes	
B-9	B	3	1	0.5	1	0	0	Yes	
B-10	B	2	1	0.5	9	0	0	Yes	
B-10	B	288	0.25	0.25	0	1	0	Yes	
B-12	B	2	1	0.25	1	0	0	Yes	
C-1	C	120	0.25	0.25	0	1	0	Yes	
C-1	C	2	1	0.25	3	0	0	Yes	
C-1	C	1	1	0.5	2	0	0	Yes	
C-2	C	5	1	0.25	4	0	0	Yes	
C-2	C	18	3	0.25	2	0	0	Yes	
C-3	C	3	1	0.25	5	0	0	Yes	
C-5	C	3	2	0.25	8	0	0	Yes	
C-7	C	4	1	0.25	4	0	0	Yes	
C-7	C	144	0.25	0.25	0	2	0	Yes	
C-8	C	9	0.25	0.25	0	0	0	Yes	
C-8	C	252	0.25	0.25	0	1	0	Yes	
C-9	C	3	3	0.25	2	0	0	Yes	
C-9	C	120	0.25	0.25	0	1	0	Yes	
C-9	C	60	0.25	0.25	0	1	0	Yes	
C-9	C	102	0.25	0.25	0	1	0	Yes	
C-10	C	3	2	0.25	4	0	0	Yes	
D-1	D	2	1	0.25	5	0	0	Yes	
D-1	D	2	1	0.25	1	0	0	Yes	
D-2	D	12	0.25	0.25	0	1	0	Yes	
D-3	D	300	0.25	0.25	0	1	0	Yes	
D-3	D	2	1	0.25	2	0	0	Yes	
D-3	D	3	1	0.25	3	0	0	Yes	

D-4	D	2	1	0.25	1	0	0	Yes
D-5	D	3	1	0.25	8	0	0	Yes
D-6	D	3	0.5	0.25	0	0	0	Yes
D-6	D	4	2	0.25	1	0	0	Yes
D-8	D	5	2	0.25	1	0	0	Yes
D-7	D	2	1	0.125	3	0	0	Yes
D-8	D	84	0.25	0.25	0	1	0	Yes
D-8	D	2	1	0.25	3	0	0	Yes
D-9	D	300	0.25	0.25	0	1	0	Yes
D-9	D	216	0.25	0.25	0	1	0	Yes
D-10	D	300	0.25	0.25	0	1	0	Yes
D-10	D	36	0.25	0.25	0	1	0	Yes
E-1	E	2	1	1	3	0	0	Yes
E-1	E	10	1	0.25	6	0	0	Yes
E-2	E	4	2	0.5	2	0	0	Yes
E-1	E	24	0.25	0.125	0	0	0	Yes
O-1	O	4	4	0.5	1	0	0	Yes
E-1	E	48	0.25	0.25	0	1	0	Yes
E-1	E	3	1	0.25	3	0	0	Yes
E-1	E	2	1.5	0.25	6	0	0	Yes
E-2	E	2	0.5	0.25	1	0	0	Yes
E-3	E	96	0.25	0.25	0	1	0	Yes
E-3	E	4	1	0.25	5	0	0	Yes
E-4	E	36	0.25	0.25	0	1	0	Yes
E-4	E	1	1	0.5	7	0	0	Yes
E-5	E	108	0.25	0.25	0	1	0	Yes
E-5	E	4	2	0.25	1	0	0	Yes
E-6	E	1	1	0.25	5	0	0	Yes
E-7	E	108	0.25	0.25	0	1	0	Yes
E-7	E	3	2	0.25	1	0	0	Yes
E-9	E	36	0.25	0.125	0	0	0	Yes
E-9	E	6	4	0.125	1	0	0	Yes
E-11	E	3	3	0.25	1	0	0	Yes
F-1	F	96	0.25	0.25	0	1	0	Yes
F-1	F	4	0.5	0.25	3	0	0	Yes
F-2	F	264	0.25	0.25	0	1	0	Yes
F-4	F	3	2	0.25	3	0	0	Yes
F-5	F	4	2	0.25	9	0	0	Yes
F-5	F	3	3	0.25	9	0	0	Yes
F-5	F	4	3	0.25	2	0	0	Yes
F-6	F	36	0.25	0.25	0	1	0	Yes
F-7	F	3	2	0.125	7	0	0	Yes
F-7	F	168	0.25	0.25	0	1	0	Yes
F-7	F	3	2	0.25	4	0	0	Yes
F-8	F	2	2	1	1	0	0	Yes
G-1	G	8	4	0.125	1	0	0	Yes
G-3	G	6	4	0.25	1	0	0	Yes
G-5	G	36	0.25	0.25	0	0	0	Yes
G-5	G	3	1	0.25	1	0	0	Yes
G-7	G	4	2	0.25	1	0	0	Yes
G-11	G	3	4	0.5	1	0	0	Yes
G-11	G	3	4	0.5	1	0	0	Yes

H-1	H	96	0.25	0.25	0	1	0	Yes
H-2	H	4	1	0.125	7	0	0	Yes
H-3	H	4	1	0.125	5	0	0	Yes
H-4	H	9	3	0.25	1	0	0	Yes
H-6	H	2	1	0.3	1	0	0	Yes
H-8	H	36	0.3	0.25	0	2	0	Yes
H-11	H	156	0.25	0.25	0	1	0	Yes
H-12	H	492	0.25	0.25	0	1	0	Yes
H-12	H	372	0.25	0.25	0	1	0	Yes
I-1	I	8	2	0.25	1	0	0	Yes
I-1	I	4	1	0.25	0	0	0	Yes
I-2	I	2	2	0.25	4	0	0	Yes
I-3	I	30	0.25	0.25	0	1	0	Yes
I-3	I	2	2	0.25	4	0	0	Yes
I-7	I	5	2	0.125	1	0	0	Yes
I-9	I	8	0.25	0.25	0	1	0	Yes
J-2	J	12	2	0.25	1	0	0	Yes
J-5	J	36	0.25	0.25	0	1	0	Yes
J-5	J	6	2	0.125	5	0	0	Yes
J-6	J	5	2	0.25	0	0	0	Yes
K-1	K	8	3	0.25	1	0	0	Yes
K-2	K	6	0.25	0.25	0	1	0	Yes
K-12	K	24	1.5	0.25	1	0	0	Yes
K-12	K	5	1	0.25	1	0	0	Yes
M-1	M	3	1	0.25	7	0	0	Yes
M-1	M	288	0.25	0.25	0	1	0	Yes
M-2	M	3	1	0.25	1	0	0	Yes
M-2	M	72	0.25	0.25	0	1	0	Yes
M-2	M	1	1	0.25	12	0	0	Yes
M-2	M	384	0.25	0.25	0	1	0	Yes
M-3	M	192	0.25	0.25	0	1	0	Yes
M-4	M	36	0.25	0.25	0	1	0	Yes
M-4	M	36	0.25	0.25	0	0	0	Yes
M-4	M	4	2	0.25	4	0	0	Yes
M-4	M	120	0.25	0.25	0	1	0	Yes
M-5	M	3	1	0.25	1	0	0	Yes
M-5	M	168	0.25	0.25	0	1	0	Yes
M-6	M	5	4	0.25	1	0	0	Yes
O-4	O	7	4	0.5	1	0	0	Yes
Entry Way	Entry Way	12	3	0.25	1	0	0	Yes
Entry Way	Entry Way	4	3	0.25	1	0	0	Yes
Club House	Club House	5	4	0.25	1	0	0	Yes
O-9	O	6	1	0.125	4	0	0	Yes
O-1	O	36	0.25	0.125	0	0	0	Yes
O-1	O	36	0.25	0.125	0	0	0	Yes
O-8	O	144	0.25	0.25	0	1	0	Yes
O-10	O	2	2	0.25	4	0	0	Yes
O-6	O	5	1	0.25	1	0	0	Yes
O-1	O	4	1	0.25	1	0	0	Yes
O-1	O	144	0.25	0.25	0	0	0	Yes
O-2	O	36	0.25	0.25	0	0	0	Yes
O-4	O	24	0.25	0.5	0	0	0	Yes

O-6	O	4	1	0.25	2	0	0	Yes	entry
O-6	O	36	0.25	0.4	0	0	0	Yes	entry
O-6	O	2	1	0.25	2	0	0	Yes	entry
O-7	O	144	0.25	0.25	0	1	0	Yes	entry
O-10	O	144	0.25	0.25	0	1	0	Yes	slab 1
O-10	O	3	3	0.25	3	0	0	Yes	slab 3
O-10	O	144	0.25	0.25	0	1	0	Yes	slab 3
O-9	O	144	0.25	0.25	0	1	0	Yes	slab 4
O-8	O	5	2	0.25	7	0	0	Yes	slab 5
O-9	O	144	0.25	0.25	0	1	0	Yes	slab 5
O-8	O	144	0.25	0.25	0	1	0	Yes	slab 6
O-6	O	360	0.25	0.25	0	1	0	Yes	slab 7
O-6	O	36	0.25	0.25	2	0	0	Yes	slab 8 needs rep
O-5	O	300	0.25	0.25	0	1	0	Yes	slab 10
O-4	O	144	0.25	0.25	0	1	0	Yes	slab 12
O-4	O	48	0.25	0.25	0	0	0	Yes	slab 12
O-3	O	144	0.25	0.25	0	1	0	Yes	slab 13
O-2	O	2	1	0.25	2	0	0	Yes	slab 14
O-1	O	144	0.25	0.25	0	0	0	Yes	slab 19
O-1	O	144	0.25	0.25	0	0	0	Yes	slab 20
Club House	Club House	2	2	0.5	3	0	0	Yes	
Club House	Club House	336	0.25	0.25	0	1	0	Yes	
Club House	Club House	5	1	0.25	1	0	0	Yes	
N-5	N	48	0.33	0.25	0	0	0	Yes	
N-1	N	3	1	0.33	5	0	0	Yes	
N-3	N	3	1	0.25	7	0	0	Yes	
N-4	N	120	0.25	0.25	0	1	0	Yes	
N-4	N	96	2	0.25	1	0	0	Yes	
N-5	N	3	1	0.25	2	0	0	Yes	
N-6	N	192	0.25	0.25	0	1	0	Yes	
N-8	N	48	0.25	0.25	0	0	0	Yes	
N-11	N	7	1	0.25	2	0	0	Yes	
N-11	N	120	0.25	0.25	0	1	0	Yes	
N-10	N	120	0.25	0.25	0	1	0	Yes	
N-9	N	120	0.25	0.25	0	1	0	Yes	
N-7	N	36	0.25	0.25	0	0	0	Yes	
N-6	N	60	0.25	0.25	0	0	0	Yes	
N-1	N	24	0.25	0.25	0	0	0	Yes	
U-10	U	6	2	1	1	0	0	Yes	
T-10	T	12	1	0.25	1	0	0	Yes	
U-6	U	36	0.25	0.25	0	0	0	Yes	
U-1	U	120	0.25	0.25	0	1	0	Yes	
U-1	U	3	1	0.25	9	0	0	Yes	
U-4	U	5	2	0.25	1	0	0	Yes	
U-5	U	6	2	0.25	1	0	0	Yes	
U-7	U	5	5	0.25	1	0	0	Yes	
U-10	U	3	2	0.25	2	0	0	Yes	
T-1	T	2	1	0.25	3	0	0	Yes	
T-8	T	4	4	0.25	1	0	0	Yes	
T-12	T	4	1	0.5	1	0	0	Yes	
S-5	S	1	1	0.25	12	0	0	Yes	
S-10	S	3	1	0.25	27	0	0	Yes	

R-1	R	168	0.25	0.25	0	0	0	Yes	
R-1	R	12	0.5	0.25	0	1	0	Yes	
Q-4	Q	3	1	0.25	4	0	0	Yes	
Q-4	Q	144	0.25	0.25	0	1	0	Yes	
Q-9	Q	4	2	0.25	4	0	0	Yes	
P-10	P	3	1	0.25	12	0	3	Yes	across 3 slabs
P-10	P	72	0.25	0.25	0	0	0	Yes	
P-10	P	5	4	0.5	1	0	0	Yes	
P-10	P	3	1	0.25	9	0	0	Yes	
P-10	P	144	0.3	0.25	0	1	0	Yes	
S-3	S	48	0.25	0.25	0	0	0	Yes	
S-10	S	4	1	0.25	1	0	0	Yes	
S-10	S	120	0.25	0.25	0	1	0	Yes	
S-10	S	120	0.25	0.25	0	1	0	Yes	
S-10	S	120	0.25	0.25	0	1	0	Yes	
S-10	S	360	0.25	0.25	0	1	0	Yes	
S-4	S	7	2	0.25	1	0	0	Yes	
S-1	S	120	0.25	0.25	0	0	0	Yes	
S-1	S	3	2	0.25	1	0	0	Yes	
R-1	R	36	0.25	0.25	0	0	0	Yes	
R-1	R	36	0.25	0.25	0	0	0	Yes	
R-6	R	36	0.25	0.25	0	0	0	Yes	
Q-5	Q	36	0.25	0.25	0	0	0	Yes	
Q-1	Q	240	0.25	0.25	0	1	0	Yes	
P-1	P	62	0.25	0.25	0	0	0	Yes	
P-1	P	3	1	0.25	3	0	0	Yes	
P-2	P	3	1	0.25	3	0	0	Yes	
P-2	P	48	0.25	0.25	0	0	0	Yes	
P-3	P	144	0.25	0.25	0	0	0	Yes	
P-8	P	48	0.25	0.25	0	0	0	Yes	
P-9	P	144	0.25	0.25	0	0	0	Yes	
P-9	P	96	0.25	0.25	0	0	0	Yes	
P-10	P	4	0.5	0.25	5	0	0	Yes	
P-10	P	48	0.25	0.25	0	0	0	Yes	
P-10	P	72	0.25	0.25	0	0	0	Yes	
P-10	P	3	1	0.25	1	0	0	Yes	
P-10	P	4	1	0.25	4	1	0	Yes	
P-10	P	96	0.25	0.25	0	1	0	Yes	
P-10	P	96	0.25	0.25	0	0	0	Yes	
P-10	P	120	0.25	0.25	0	0	0	Yes	
P-10	P	48	0.25	0.25	0	0	0	Yes	
P-10	P	3	1	0.25	1	0	0	Yes	
P-10	P	4	2	0.25	1	0	0	Yes	
P-10	P	120	0.25	0.25	0	0	0	Yes	
P-10	P	120	0.25	0.25	0	0	0	Yes	
P-10	P	5	2	0.25	1	0	0	Yes	
G-2	G				0	0	2	Yes	single lane near
A-3	A	120	0.25	0.25	0	1	0	Yes	
A-5	A	300	0.25	0.25	0	1	0	Yes	
A-6	A	96	0.5	0.25	0	1	0	Yes	
A-6	A	60	0.5	0.25	0	1	0	Yes	
A-10	A	4	2	0.25	2	0	0	Yes	

B-1	B	24	0.25	0.25	0	1	0	Yes
B-1	B	84	0.25	0.25	0	1	0	Yes
B-2	B	84	0.25	0.25	0	1	0	Yes
B-2	B	168	0.25	0.25	0	1	0	Yes
B-3	B	192	0.25	0.25	0	1	0	Yes
B-3	B	84	0.25	0.25	0	1	0	Yes
B-4	B	168	0.25	0.25	0	1	0	Yes
B-4	B	84	0.25	0.25	0	1	0	Yes
B-6	B	96	0.25	0.25	0	1	0	Yes
B-7	B	384	0.25	0.25	0	1	0	Yes
B-8	B	384	0.25	0.25	0	1	0	Yes
B-8	B	36	0.25	0.25	0	1	0	Yes
B-9	B	72	0.25	0.25	0	1	0	Yes
B-10	B	120	0.25	0.25	0	1	0	Yes
B-11	B	96	0.25	0.25	0	1	0	Yes
B-11	B	120	0.25	0.25	0	1	0	Yes
B-12	B	120	0.25	0.25	0	1	0	Yes
B-12	B	120	0.25	0.25	0	1	0	Yes
B-12	B	24	0.25	0.25	0	3	0	Yes
B-12	B	120	0.25	0.25	0	3	0	Yes
B-12	B	96	0.25	0.25	0	1	0	Yes
B-12	B	14	8	0.25	0	0	0	Yes
B-12	B	36	0.25	0.25	0	1	0	Yes
C-1	C	252	0.25	0.25	0	4	0	Yes
C-1	C	276	0.25	0.25	0	1	0	Yes
C-1	C	5	1	0.25	2	0	0	Yes
C-1	C	324	0.25	0.25	0	1	0	Yes
C-1	C	102	0.25	0.25	0	1	0	Yes
C-1	C	30	0.25	0.25	0	1	0	Yes
C-2	C	114	0.25	0.25	0	1	0	Yes
C-2	C	120	0.25	0.25	0	1	0	Yes
C-2	C	96	0.25	0.25	0	1	0	Yes
C-2	C	180	0.25	0.25	0	1	0	Yes
C-3	C	252	0.25	0.25	0	1	0	Yes
C-3	C	84	0.25	0.25	0	1	0	Yes
C-3	C	2	0.5	0.25	6	0	0	Yes
C-3	C	216	0.25	0.25	0	1	0	Yes
C-4	C	72	0.25	0.25	0	1	0	Yes
C-4	C	336	0.25	0.25	0	1	0	Yes
C-4	C	336	0.25	0.25	0	1	0	Yes
C-5	C	168	0.25	0.25	0	1	0	Yes
C-5	C	120	0.25	0.25	0	1	0	Yes
C-7	C	174	0.25	0.25	0	1	0	Yes
C-7	C	5	0.25	0.25	0	1	0	Yes
C-7	C	86	0.25	0.25	0	1	0	Yes
C-8	C	174	0.25	0.25	0	1	0	Yes
C-10	C	17	6	1	1	0	0	Yes
D-1	D	180	0.25	0.25	0	1	0	Yes
D-2	D	120	0.25	0.25	0	1	0	Yes
D-2	D	96	0.25	0.25	0	1	0	Yes
D-2	D	24	0.25	0.25	0	1	0	Yes
D-3	D	96	0.25	0.25	0	1	0	Yes

D-3	D	96	0.25	0.25	0	1	0	Yes
D-4	D	84	0.25	0.25	0	1	0	Yes
D-4	D	84	0.25	0.25	0	1	0	Yes
D-4	D	156	0.25	0.25	0	1	0	Yes
D-5	D	84	0.25	0.25	0	1	0	Yes
D-8	D	1	1	0.25	1	0	0	Yes
D-7	D	2	1	0.25	2	0	0	Yes
D-7	D	84	0.25	0.25	0	1	0	Yes
D-7	D	84	0.25	0.25	0	1	0	Yes
D-8	D	84	0.25	0.25	0	1	0	Yes
D-8	D	1	1	0.125	1	0	0	Yes
E-1	E	1	1	0.25	5	0	0	Yes
E-1	E	264	0.25	0.25	0	1	0	Yes
E-1	E	384	0.25	0.25	0	1	0	Yes
O-1	O	24	0.25	0.25	0	1	0	Yes
O-1	O	3	3	0.125	1	0	0	Yes
E-1	E	4	2	1.5	1	0	0	Yes
E-1	E	2	2	0.25	4	0	0	Yes
E-1	E	72	0.25	0.25	0	1	0	Yes
E-1	E	300	0.25	0.25	0	1	0	Yes
E-1	E	96	0.25	0.25	0	1	0	Yes
E-2	E	86	0.25	0.25	0	1	0	Yes
E-3	E	84	0.25	0.25	0	1	0	Yes
E-3	E	3	1	0.25	1	0	0	Yes
E-3	E	96	0.25	0.25	0	1	0	Yes
E-3	E	192	0.25	0.25	0	1	0	Yes
E-3	E	180	0.25	0.25	0	1	0	Yes
E-3	E	96	0.25	0.25	0	1	0	Yes
E-4	E	6	1	0.25	1	0	0	Yes
E-4	E	144	0.25	0.25	0	1	0	Yes
E-5	E	2	1	0.25	5	0	0	Yes
E-5	E	144	0.25	0.25	0	1	0	Yes
E-6	E	4	2	0.25	1	0	0	Yes
E-6	E	108	0.25	0.25	0	1	0	Yes
E-6	E	108	0.25	0.25	0	1	0	Yes
E-7	E	96	0.25	0.25	0	1	0	Yes
E-7	E	252	0.25	0.25	0	1	0	Yes
E-7	E	4	3	0.125	1	0	0	Yes
E-7	E	108	0.25	0.25	0	1	0	Yes
E-8	E	1	1	0.25	4	0	0	Yes
E-8	E	0.5	0.5	0.25	1	0	0	Yes
E-9	E	2	1	0.125	3	0	0	Yes
E-9	E	0.5	0.5	0.25	7	1	0	Yes
E-10	E	2	1	0.25	6	0	0	Yes
E-10	E	192	0.25	0.25	0	1	0	Yes
E-11	E	168	0.25	0.25	0	1	0	Yes
E-12	E	1	1	0.125	1	0	0	Yes
E-12	E	2	1	0.25	1	0	0	Yes
F-1	F	96	0.25	0.25	0	1	0	Yes
F-1	F	2	1	0.125	3	0	0	Yes
F-2	F	2	1	0.125	1	0	0	Yes
F-2	F	480	0.125	0.25	0	1	0	Yes

F-3	F	1	0.5	0.125	10	0	0	Yes
F-3	F	3	1	0.25	1	0	0	Yes
F-4	F	36	0.125	0.25	0	1	0	Yes
F-4	F	1	0.5	0.25	4	0	0	Yes
F-5	F	24	0.125	0.25	0	1	0	Yes
F-7	F	0.5	0.5	0.25	1	0	0	Yes
F-8	F	5	0.5	0.125	0	0	0	Yes
F-8	F	1	0.5	0.25	1	0	0	Yes
F-12	F	240	0.25	0.25	0	1	0	Yes
G-4	G	18	0.25	0.25	0	1	0	Yes
G-6	G	2	0.5	0.25	3	0	0	Yes
G-7	G	1	0.5	0.25	3	0	0	Yes
G-9	G	84	0.125	0.25	0	1	0	Yes
G-11	G	1	1	0.25	1	0	0	Yes
G-11	G	1	1	0.25	1	0	0	Yes
H-1	H	108	0.125	0.25	0	1	0	Yes
H-1	H	120	0.25	0.25	0	1	0	Yes
H-3	H	120	0.125	0.125	0	1	0	Yes
H-4	H	36	0.25	0.25	0	1	0	Yes
H-5	H	2	1	0.25	1	0	0	Yes
I-1	I	72	0.25	0.25	0	1	0	Yes
I-2	I	192	0.25	0.25	0	1	0	Yes
I-3	I	246	0.25	0.25	0	1	0	Yes
I-6	I	1	,3	0.25	2	0	0	Yes
I-7	I	6	3	1	1	0	0	Yes
B-6	B	240	0.25	0.25	0	1	0	Yes
I-7	I	48	0.25	0.25	0	1	0	Yes
I-7	I	144	0.25	0.25	0	1	0	Yes
I-10	I	86	0.125	0.25	0	1	0	Yes
I-11	I	30	0.25	0.25	0	1	0	Yes
I-11	I	84	0.125	0.25	0	1	0	Yes
J-2	J	6	0.125	0.25	0	1	0	Yes
J-2	J	4	2	0.125	1	0	0	Yes
J-3	J	48	0.125	0.25	0	1	0	Yes
J-3	J	36	0.125	0.25	0	1	0	Yes
J-4	J	60	0.125	0.25	0	1	0	Yes
J-5	J	10	3	0.125	1	0	0	Yes
J-5	J	2	1	0.25	5	0	0	Yes
J-6	J	2	0.5	0.25	6	0	0	Yes
J-8	J	2	1	0.25	3	0	0	Yes
K-1	K	216	0.25	0.25	0	1	0	Yes
K-1	K	5	3	0.25	5	0	0	Yes
K-1	K	240	0.125	0.25	0	1	0	Yes
K-1	K	120	0.125	0.25	0	1	0	Yes
K-5	K	144	0.25	0.25	0	1	0	Yes
K-6	K	2	0.5	0.25	3	0	0	Yes
K-6	K	2	0.5	0.25	3	0	0	Yes
L-5	L	4	0.3	0.25	1	0	0	Yes
L-12	L	14	0.125	0.25	0	1	0	Yes
M-4	M	192	0.25	0.25	0	1	0	Yes
M-5	M	7	4	2	1	0	0	Yes
M-6	M	5	2	0.125	1	0	0	Yes

Missing piece or

M-7	M	3	0.5	0.25	1	0	0	Yes	
M-8	M	120	0.125	0.25	0	1	0	Yes	
M-7	M	4	2	0.125	1	0	0	Yes	
M-10	M	2	2	0.25	1	0	0	Yes	
O-6	O	24	0.125	0.25	0	1	0	Yes	
Entry Way	Entry Way	3	3	0.125	1	0	0	Yes	
Entry Way	Entry Way	8	4	0.25	1	0	0	Yes	
O-3	O	1	0.5	0.25	2	0	0	Yes	
O-3	O	48	10	1	1	0	0	Yes	
O-1	O	2	12	0.25	2	0	0	Yes	
O-6	O	36	0.25	0.36	0	0	0	Yes	
O-6	O	36	0.25	0.25	0	0	0	Yes	
O-8	O	36	0.25	0.25	0	0	0	Yes	
O-10	O	240	0.25	0.25	0	1	0	Yes	
O-9	O	2	2	0.25	1	0	0	Yes	
O-8	O	120	0.25	0.25	0	1	0	Yes	
O-6	O	3	0.5	0.25	2	0	0	Yes	
O-2	O	120	0.25	0.25	0	1	0	Yes	
O-2	O	2	1	0.25	1	0	0	Yes	
O-1	O	3	1	0.25	1	0	0	Yes	
O-1	O	5	1	0.25	2	0	0	Yes	
O-1	O	3	1	0.25	1	0	0	Yes	
O-2	O	384	0.25	0.25	0	0	0	Yes	
O-6	O	4	1	0.25	4	0	0	Yes	entry
O-6	O	5	4	0.25	22	0	0	Yes	slab 8 needs re
O-6	O	432	0.25	0.25	0	1	0	Yes	slab 8 needs re
O-6	O	360	0.25	0.25	0	1	0	Yes	slab 8 needs re
O-5	O	3	2	0.25	8	0	0	Yes	slab 9
O-5	O	360	0.25	0.25	0	1	0	Yes	slab 9
O-5	O	12	0.25	0.5	0	0	0	Yes	slab 10
O-1	O	88	0.25	0.25	0	1	0	Yes	slab 16 needs re
O-1	O	200	0.25	0.25	0	1	0	Yes	slab 16 needs re
O-1	O	30	0.25	0.5	0	0	0	Yes	slab 17
O-1	O	48	0.25	0.25	0	1	0	Yes	slab 17
Club House	Club House	1	1	0.25	1	0	0	Yes	
Club House	Club House	168	0.25	0.25	0	1	0	Yes	
Club House	Club House	168	0.25	0.25	0	1	0	Yes	
Club House	Club House	144	0.25	0.25	0	1	0	Yes	
Club House	Club House	144	0.25	0.25	0	1	0	Yes	
Club House	Club House	144	0.25	0.25	0	1	0	Yes	
Club House	Club House	144	0.25	0.25	0	1	0	Yes	
Club House	Club House	72	0.25	0.25	0	1	0	Yes	
N-10	N	144	0.25	0.25	0	1	0	Yes	
N-10	N	36	0.25	0.25	0	1	0	Yes	
N-12	N	6	6	0.25	1	0	0	Yes	
N-1	N	240	0.25	0.25	0	1	0	Yes	
N-3	N	384	0.25	0.25	0	1	0	Yes	
N-9	N	96	0.25	0.25	0	1	0	Yes	
N-9	N	120	0.25	0.25	0	1	0	Yes	
N-8	N	120	0.25	0.25	0	1	0	Yes	
N-7	N	120	0.25	0.25	0	1	0	Yes	
N-7	N	120	0.25	0.25	0	1	0	Yes	

N-7	N	120	0.25	0.25	0	1	0	Yes
N-6	N	168	0.25	0.25	0	1	0	Yes
N-5	N	2	1	0.25	4	0	0	Yes
N-5	N	120	0.25	0.25	0	1	0	Yes
N-4	N	360	0.25	0.25	0	1	0	Yes
N-2	N	120	0.25	0.25	0	1	0	Yes
N-1	N	120	0.25	0.25	0	1	0	Yes
N-1	N	120	0.25	0.25	0	1	0	Yes
T-1	T	168	0.25	0.25	0	1	0	Yes
U-9	U	36	0.25	0.25	0	0	0	Yes
K-12	K	36	0.25	0.25	0	1	0	Yes
K-12	K	218	0.25	0.25	0	1	0	Yes
U-2	U	2	2	0.25	0	0	0	Yes
U-2	U	120	0.25	0.25	0	1	0	Yes
U-3	U	120	0.25	0.25	0	1	0	Yes
U-4	U	120	0.25	0.25	0	1	0	Yes
U-10	U	12	2	0.25	1	0	0	Yes
U-10	U	3	1	0.25	1	0	0	Yes
U-10	U	96	0.25	0.25	0	1	0	Yes
U-10	U	72	0.25	0.25	0	0	0	Yes
T-1	T	4	1	0.25	1	0	0	Yes
T-1	T	72	0.25	0.25	0	0	0	Yes
T-1	T	1	1	0.25	2	0	0	Yes
T-1	T	120	0.25	0.25	0	1	0	Yes
T-1	T	120	0.25	0.25	0	1	0	Yes
T-1	T	2	1	0.25	2	0	0	Yes
T-11	T	4	1	0.25	1	0	0	Yes
S-10	S	504	0.25	0.25	0	1	0	Yes
R-1	R	168	0.25	0.25	0	1	0	Yes
Q-9	Q	144	0.25	0.25	0	1	0	Yes
P-7	P	288	0.25	0.25	0	1	0	Yes
P-10	P	2	1	0.25	3	0	0	Yes
P-10	P	2	1	0.25	3	0	0	Yes
S-3	S	144	0.25	0.25	0	1	0	Yes
S-4	S	24	0.25	0.25	0	1	0	Yes
S-6	S	36	0.25	0.25	0	0	0	Yes
S-6	S	120	0.25	0.25	0	1	0	Yes
S-6	S	36	0.25	0.25	0	0	0	Yes
S-10	S	1	1	0.25	1	0	0	Yes
S-9	S	240	0.25	0.25	0	1	0	Yes
S-7	S	120	0.25	0.25	0	0	0	Yes
S-5	S	240	0.25	0.25	0	1	0	Yes
S-3	S	120	0.25	0.25	0	1	0	Yes
S-1	S	120	0.25	0.25	0	1	0	Yes
R-6	R	46	0.25	0.25	0	1	0	Yes
R-10	R	36	0.25	0.25	0	0	0	Yes
R-10	R	120	0.25	0.25	0	1	0	Yes
R-7	R	3	0.5	0.25	7	0	0	Yes
R-7	R	324	0.25	0.25	0	1	0	Yes
R-6	R	48	0.25	0.25	0	1	0	Yes
R-2	R	112	0.25	0.25	0	0	0	Yes
R-1	R	4	1	0.25	2	0	0	Yes

bottom of posts

R-1	R	108	0.25	0.25	0	1	0	Yes
R-1	R	108	0.25	0.25	0	1	0	Yes
R-1	R	5	2	0.25	1	0	0	Yes
R-1	R	3	1	0.25	4	0	0	Yes
Q-1	Q	2	1	0.25	1	0	0	Yes
P-8	P	36	0.25	0.25	0	0	0	Yes
P-10	P	36	0.25	0.25	0	0	0	Yes
P-10	P	36	0.25	0.25	0	0	0	Yes
Q-1	Q	36	0.25	0.25	0	0	0	Yes
Q-4	Q	120	0.25	0.25	0	1	0	Yes
Q-5	Q	240	0.25	0.25	0	1	0	Yes
Q-5	Q	36	0.25	0.25	0	0	0	Yes
Q-6	Q	120	0.25	0.25	0	1	0	Yes
Q-9	Q	36	0.25	0.25	0	0	0	Yes
Q-10	Q	3	1	0.25	2	0	0	Yes
Q-10	Q	2	1	0.25	3	0	0	Yes
Q-10	Q	1	1	0.25	3	0	0	Yes
Q-10	Q	24	0.25	0.25	0	0	0	Yes
P-1	P	2	2	0.25	1	0	0	Yes
P-2	P	3	1	0.25	4	0	0	Yes
P-3	P	3	0.25	0.25	0	0	0	Yes
P-3	P	4	0.5	0.25	3	0	0	Yes
P-3	P	144	0.25	0.25	0	0	0	Yes
P-4	P	288	0.25	0.25	0	1	0	Yes
P-8	P	144	0.25	0.25	0	1	0	Yes
P-9	P	144	0.25	0.25	0	0	0	Yes
P-10	P	72	0.25	0.25	0	0	0	Yes
P-10	P	48	0.25	0.25	0	0	0	Yes
P-10	P	4	1	0.25	2	1	0	Yes
rack inches		40,503			voids	1,081		805
crack miles		0.00						0%
								806

ave a depth of 2.25 inches, way deeper than the 1.4 inch average.
ave a depth of 3 inches, way deeper than the 1.4 inch average.